

**KHNP****KOREA HYDRO & NUCLEAR POWER CO., LTD**

70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA

Tel: +82-42-870-5400 / Fax: +82-42-870-5449

<http://www.khnp.co.kr>

November 15, 2016
Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Attention: Mr. Jeff Ciocco
Division of New Reactor Licensing

Docket No. 52-046
MKD/NW-16-1106L

Subject: Revised Response to RAI 319-8360 for Question 03.09.03-2 (Rev. 2)

References: 1) NRC Request for Additional Information 319-8360, dated November 24, 2015
2) KHNP Letter MKD/NW-16-0716L, Response to RAI 319-8360 for Question 03.09.03-2, dated July 6, 2016
3) KHNP Letter MKD/NW-16-0908L, Revised Response to RAI 319-8360 for Question 03.09.03-2, dated August 19, 2016

KHNP is hereby submitting a revised response to RAI 319-8360, dated November 24, 2015. The revised response addresses Question 03.09.03-2 to clarify that piping loads due to internal pressure are not transferred to their associated supports. The enclosure provides the revised response to RAI 319-8360 for Question 03.09.03-2 (Rev. 2) (Non-Proprietary).

If additional information or clarification is required, please contact Daegeun Ahn, Director of KHNP Washington DC Center at ahn.daegeun@khnp.co.kr or 703-388-0592.

Sincerely,

Jae-yong Lee
Project Manager
Advanced Reactors Development Laboratory
Korea Hydro and Nuclear Power Co., Ltd

Enclosure: Revised Response to RAI 319-8360 for Question 03.09.03-2 (Rev. 2) (Non-Proprietary)

Enclosure

Revised Response to RAI 319-8360 for Question 03.09.03-2 (Rev. 2)

(Non-Proprietary)

November 15, 2016