

# SOLIS

MAIN 949.443.2290

940 Calle Negocio, Suite 250

FAX 949.248.8621

San Clemente, CA 92673

SolisUSA.com


October 31<sup>st</sup>, 2016

**Director of FSME  
Attn: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001**

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on October 28<sup>th</sup>, 2016 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRB Technologies Inc. 2580 Landmark Dr, Winston-Salem, NC 27103 North Carolina License # 034-0534-2. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Jeanette Straley at 949-429-1744.

Sincerely,



Jeanette Straley

Solis Lighting and Electrical Services, Inc

Manufacturer Name	Model Number	Serial Number	Date of Manufacture	Active (Ci or TBq amount)
Shield Source Incorporated	2000	Y29027	06/2008	0.278
Shield Source Incorporated	2000	Y29028	06/2008	0.278
Shield Source Incorporated	2000	Y29022	06/2008	0.278
Shield Source Incorporated	2000	Y29021	06/2008	0.278
Shield Source Incorporated	2000	Z15772	05/2009	0.278
Shield Source Incorporated	2000	Z15770	05/2009	0.278
Shield Source Incorporated	2000	Y29023	06/2008	0.278
Shield Source Incorporated	2000	Y29024	06/2008	0.278
Shield Source Incorporated	2000	357879	01/2006	7.5
Shield Source Incorporated	2000	357880	01/2006	7.5
Isolite Safety Light Corporation	2000	A1N1701	11/2001	7.5
Isolite Safety Light Corporation	2000	A1N1700	11/2001	7.5
Isolite Safety Light Corporation	2000	A963025	06/1999	7.5
Isolite Safety Light Corporation	2000	A46028	06/1994	7.5
Isolite Safety Light Corporation	2000	A46023	06/1994	7.5
Isolite Safety Light Corporation	2000	A46025	06/1994	7.5
Isolite Safety Light Corporation	2000	A251775	05/2002	7.5
Safety Light Corporation	2000	361841	02/2006	7.5
Safety Light Corporation	2000	326321	06/2005	7.5
Safety Light Corporation	2000	726956	08/2007	7.5
Isolite Safety Light Corporation	2000	A251770	05/2002	7.5
Isolite Safety Light Corporation	2000	A251770	05/2002	7.5
Isolite Safety Light Corporation	2000	A251773	05/2002	7.5
Isolite Safety Light Corporation	2000	A251773	05/2002	7.5
Isolite Safety Light Corporation	2000	A251781	05/2002	7.5
Isolite Safety Light Corporation	2000	A251781	05/2002	7.5
Isolite Safety Light Corporation	2000	A251766	05/2002	7.5
Isolite Safety Light Corporation	2000	A251766	05/2002	7.5
Isolite Safety Light Corporation	2000	A251768	05/2002	7.5
Isolite Safety Light Corporation	2000	A251768	05/2002	7.5
Isolite Safety Light Corporation	2000	A251776	05/2002	7.5
Isolite Safety Light Corporation	2000	A251776	05/2002	7.5
Isolite Safety Light Corporation	2000	A32290	02/1993	7.5
Isolite Safety Light Corporation	2000	A46017	06/1994	7.5
Isolite Safety Light Corporation	2000	A46016	06/1994	7.5
Isolite Safety Light Corporation	2000	A91126	01/1999	7.5
Isolite Safety Light Corporation	2000	A251359	05/2002	7.5
Isolite Safety Light Corporation	2000	A251359	05/2002	7.5
Isolite Safety Light Corporation	2000	A022297	02/2000	7.5
Isolite Safety Light Corporation	2000	A91126	01/1999	7.5