

1717 Wakonade Drive
Welch, MN 55089

800.895.4999
xcelenergy.com



DEC 01 2016

L-PI-16-098
10 CFR 21.21(a)(2)

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Prairie Island Nuclear Generating Plant, Unit 1
Docket No. 50-282
Renewed Facility Operating License No. DPR-42

Followup to Interim Report Submitted under 10 CFR 21.21(a)(2)

Reference:

1. S. Northard, NSPM, letter to NRC Document Control Desk, "Interim Report of a Deviation or Failure to Comply," L-PI-16-089, 11/04/2016 (ADAMS Accession Number ML16309A597)

Northern States Power Company, a Minnesota Corporation, (NSPM), doing business as Xcel Energy, hereby submits this followup report to the interim report (Reference 1) submitted pursuant to 10 CFR 21.21(a)(2) regarding a failed bench test of a Clark Relay Model 4U3-130.

NSPM returned the relay to the vendor to evaluate. The vendor's as-found inspection identified that the threads of the upper fixed contact mounting screw of the third pole were stripped out. The vendor's Commercial Grade Dedication (CGD) process includes checking for this stripped condition. Therefore, the vendor concluded the relay was damaged at Prairie Island Nuclear Generating Plant. No nonconformance was identified, and the relay was not modified, or altered, or repaired. As a result, this condition is not reportable under 10 CFR 21.

If there is any question or if additional information is needed, please contact Frank Sienczak, at 651-267-1740.

Summary of Commitments

This letter makes no new commitments and no revisions to existing commitments.

A handwritten signature in black ink, appearing to read "Scott Northard", written in a cursive style.

Scott Northard
Site Vice President, Prairie Island Nuclear Generating Plant
Northern States Power Company – Minnesota

cc: Administrator, Region III, USNRC
Project Manager, Prairie Island, USNRC
Resident Inspector, Prairie Island, USNRC