

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Princeton Hydro, LLC 1200 Liberty Place Sicklerville, New Jersey 08081 REPORT NUMBER(S) 2016-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713
3. DOCKET NUMBER(S) 030-36110	4. LICENSE NUMBER(S) 29-30767-01	5. DATE(S) OF INSPECTION 10/14, 10/20 and 11/10/16

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):

- ☒ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

10 CFR 30.36(d) requires, in part, that licensees provide notification to the NRC in writing within 60 days of any of the following occurrences: (1) The license has expired, (2) The licensee has decided to permanently cease principal activities at the entire site or in any separate building or outdoor area that contains residual radioactivity such that the building or outdoor area is unsuitable for release in accordance with NRC requirements, (3) No principal activities under the license have been conducted for a period of 24 months, or (4) No principal activities have been conducted for a period of 24 months in any separate building or outdoor area that contains residual radioactivity such that the building or outdoor area is unsuitable for release in accordance with NRC requirements.

Contrary to the above, as of November 10, 2016, the licensee had not conducted principal activities under the license for a period of 24 months, and the licensee failed to notify the NRC in writing within 60 days of this occurrence.

This is a Severity Level IV violation (6.3).

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	RICHARD ROGERS	<i>Richard Rogers</i>	11/15/16
NRC INSPECTOR	Betsy Ullrich, Senior Health Physicist	<i>Betsy Ullrich</i>	11/10/16

BRANCH CHIEF	BLAKE WELLING	<i>Blake Well</i>	11/29/16
--------------	---------------	-------------------	----------

*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013)

G:\WordDocs\Current\Insp Record\IR29-30767-01.2016-001.591M-Part1.doc

SUNSI Review Completed By:

/ RA /

Blake Well

☒

Public

☒

Non-Sensitive