

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N Y N M P 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE 57 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 2 2 0 7 0 8 2 2 8 0 8 0 9 1 9 8 0 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
DOCKET NUMBER EVENT DATE REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation excessive outboard seal water leakage was  
0 3 observed on #11 Reactor Feedwater Pump. This had no immediate adverse  
0 4 effect on pump or plant safe operation.  
0 5  
0 6  
0 7  
0 8  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
C H 11 E 12 F 13 P U M P X X 14 B 15 Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
17 8 0 0 1 7 0 3 L 0  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPFD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
A 18 Z 19 B 20 Z 21 0 0 5 1 N 23 Y 24 N 25 W 3 1 5 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The leakage is attributed to normal seal wear fatigue. Planned power reduction  
1 1 to remove the component from service for repairs was performed. The high  
1 2 pressure coolant injection with an inoperable component test was satisfactorily  
1 3 completed to prove redundant component operability. The required maintenance  
1 4 was performed and the pump was returned to service with acceptable seal performance.  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 5 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
E 28 0 8 2 29 N/A B 31 OPERATOR OBSERVATION  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
Z 33 Z 34 N/A N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
0 0 0 37 Z 38 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION  
0 0 0 40 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
Z 42 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 PUBLICITY ISSUED DESCRIPTION  
N 44 N/A  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NRC USE ONLY

8009300494

NAME OF PREPARER Paul Harrison

PHONE: (315) 343-2110, X1212

