

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8302160234 DOC. DATE: 83/02/10 NOTARIZED: NO
 FACIL: 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co.
 AUTH. NAME AUTHOR AFFILIATION
 UHRIG, R.E. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 EISENHUT, D.G. Division of Licensing

DOCKET #
 05000389

SUBJECT: Provides results of evaluation of new electronic diesel generator load sequencing relays, undertaken per SER (NUREG-0843), Section 8.3.1.1. New relays will be installed by end of first refueling.

DISTRIBUTION CODE: B001S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1
 TITLE: Licensing Submittal: PSAR/FSAR Amdts & Related Correspondence

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
A/D LICENSNG	1 0	LIC BR #3 BC	1 0
LIC BR #3 LA	1 0	NERSES, V.	01 1 1
INTERNAL: ELD/HDS2	1 0	IE FILE	1 1
IE/DEP EPDS 35	1 1	IE/DEP/EPLB 36	3 3
NRR/DE/AEAB	1 0	NRR/DE/CEB 11	1 1
NRR/DE/eqB 13	2 2	NRR/DE/GB 28	2 2
NRR/DE/HGEB 30	1 1	NRR/DE/MEB 18	1 1
NRR/DE/MTB 17	1 1	NRR/DE/QAB 21	1 1
NRR/DE/SAB 24	1 1	NRR/DE/SEB 25	1 1
NRR/DHFS/HFEB40	1 1	NRR/DHFS/LQB 32	1 1
NRR/DL/SSPB	1 0	NRR/DSI/AEB 26	1 1
NRR/DSI/ASB	1 1	NRR/DSI/CPB 10	1 1
NRR/DSI/CSB 09	1 1	NRR/DSI/ICSB 16	1 1
NRR/DSI/METB 12	1 1	NRR/DSI/PSB 19	1 1
NRR/DSI/RAB 22	1 1	NRR/DSI/RSB 23	1 1
REG FILE 04	1 1	RGN2	3 3
RM/DDAMI/MIB	1 0		

EXTERNAL: ACRS 41	6 6	BNL (AMDTS ONLY)	1 1
DMB/DSS (AMDTS)	1 1	FEMA-REP DIV 39	1 1
LPDR 03	1 1	NRC PDR 02	1 1
NSIC 05	1 1	NTIS	1 1


TOTAL NUMBER OF COPIES REQUIRED: LTTR 52 ENCL 45

67

[illegible]

26, 11 11 11

1991年12月15日



February 10, 1983
L-83-61

Office of Nuclear Reactor Regulations
Attention: Mr. Darrell G. Eisenhut, Director
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Eisenhut:

Re: St. Lucie Unit No. 2
Docket No. 50-389
Diesel Generator Load
Sequencing Relays

As discussed in NUREG-0843 section 8.3.1.1, Florida Power and Light Company (FPL) has been evaluating new electronic diesel generator load sequencing relays. We have completed our evaluation and have determined that the new electronic relays will be more reliable than those presently installed. Therefore, FPL will replace the existing relays with the new electronic relays. Installation of the new relays is expected to be completed by the end of the first refueling.

If you have any questions regarding this matter, please contact us.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems and Technology

3001

REU/RJS/PPC/mp

Attachment

cc: J.P. O'Reilly, Region II
Harold F. Reis, Esquire

8302160234 830210
PDR ADCK 05000389
E PDR