



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

August 7, 1979

Mr. Boyce H. Grier, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

REGULATORY DOCKET FILE COPY

Subject: LER 79-015/01T-0, Nonconforming Pipe Supports Identified
during Response to IE Bulletin 79-14
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. Grier:

In accordance with Technical Specifications, Article 6.9.2.a(9) (discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition), Licensee Event Report LER 79-015/01T-0 was submitted in conjunction with our 30 day response to IE Bulletin 79-14, Seismic Analyses for As-built Safety Related Piping Systems. The two required additional copies of the report are attached.

Very truly yours,

L. D. White, Jr.
L. D. White, Jr.

Attachment

cc: Mr. Victor Stello, Jr. (40)
Mr. Norman R. Haller (3)

*A002
S.11*

790 8100 471²

11