




ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700



September 4, 1980

Mr. Boyce H. Grier, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: IE Bulletin No. 80-18, "Maintenance of Adequate Minimum
Flow Thru Centrifugal Charging Pumps Following Secondary
Side High Energy Line Rupture"
R. E. Ginna Nuclear Power Plant, Unit #1
Docket No. 50-244

Dear Mr. Grier:

In reply to Inspection and Enforcement Bulletin 80-18 dated
July 24, 1980, concerning the subject potential problem with centrifugal
charging pumps, Ginna Station does not utilize centrifugal charging pumps.

To assist in evaluating the value/impact of each Bulletin on
licensees, manpower expended in conduct of the review and preparation
of this report is approximately three manhours. No corrective actions
were necessary.

Very truly yours,

L. D. White, Jr.

xc: Mr. Victor Stello, Jr., Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operations Inspection
Washington, D. C. 20555

8010010788

Q

