


ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 546-2700



August 27, 1980

Mr. Boyce H. Grier, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Subject: IE Bulletin No. 80-19, Failures of Mercury-wetted Matrix  
Relays in Reactor Protective Systems of Operating Nuclear  
Power Plants Designed by Combustion Engineering, and  
Revision I to IE Bulletin No. 80-19  
R. E. Ginna Nuclear Power Plant, Unit #1  
Docket No. 50-244

Dear Mr. Grier:

In reply to Inspection and Enforcement Bulletin 80-19, dated  
July 31, 1980, and its revision dated August 15, 1980, concerning  
mercury-wetted relays, there are no mercury-wetted relays installed or  
planned for use in the Reactor Protection System at Ginna Station.

To assist in evaluating the value/impact of each Bulletin on  
licensees, manpower expended in conduct of the review and preparation  
of this report is approximately one manhour. No corrective actions were  
necessary.

Very truly yours,

*L. D. White, Jr.*  
L. D. White, Jr.

xc: Director  
Division of Reactor Operations Inspection  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

8010020095

Q

