

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9006080228 DOC.DATE: 90/05/29 NOTARIZED: YES DOCKET #
 FACIL:50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester 'G 05000244
 AUTH.NAME AUTHOR AFFILIATION
 MECREDY,R.C. Rochester Gas & Electric Corp.
 RECIP.NAME RECIPIENT AFFILIATION
 JOHNSON,A.R. Project Directorate I-3

SUBJECT: Responds to NRC Bulletin 90-001, "Loss of Fill-Oil in Transmitters Mfg by Rosemount."

DISTRIBUTION CODE: IE39D COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 2
 TITLE: NRC Bulletin 90-001, Loss of Fill Oil in Transmitters Mfg by Rosemount

NOTES:License Exp date in accordance with 10CFR2,2.109(9/19/72). 05000244

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD1-3 LA	1 0		PD1-3 PD	1 1
	JOHNSON,A	1 1			
INTERNAL:	NRR LE,N	1 1		NRR PERCH,R	1 1
	NRR RAMSEY,J	2 2		NRR/DRIS/RVIB	1 1
	<u>REG FILE</u> 02	1 1		RES FARMER,W	1 1
	RGNI FILE 01	1 1			
EXTERNAL:	LPDR	1 1		NRC PDR	1 1
	NSIC	1 1			

p34056861

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 0

AD-1
mlt

R

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001

TELEPHONE 586-2100

May 29, 1990

U.S. Nuclear Regulatory Commission
Document Control Desk
Attention: Allen R. Johnson
Project Directorate I-3
Washington, D.C. 20555

Subject: Response to Bulletin 90-01
Loss of Fill-Oil in Transmitters Manufactured
by Rosemount
R.E. Ginna Nuclear Power Plant
Docket Number 50-244

Dear Mr. Johnson:

NRC Bulletin 90-01 requested that licensees promptly identify and take appropriate corrective actions for Model 1153, Series B; Model 1153, Series D; and Model 1154 transmitters manufactured by Rosemount that may be leaking fill-oil.

This letter provides the response required by NRC Bulletin 90-01.

Rochester Gas and Electric, in accordance with requested Action Item 1, confirms that the R.E. Ginna Nuclear Power Plant does not have any Rosemount transmitters installed in either safety-related systems or systems installed in accordance with 10CFR50.62 (ATWS Rule). Requested Action Items 2, 3, 4, and 5 are, therefore, not applicable.

The eleven transmitters installed in non-safety related applications, (nine Model 1151) and (two Model 1153D), have not exhibited symptoms indicative of loss of fill-oil.


Rochester Gas and Electric does not need to develop an enhanced surveillance program to monitor currently installed Rosemount transmitters based upon the limited installed quantity (11), the low differential pressure and the non-safety related applications.

9006080228 900529
PDR ADOCK 05000244
R PDC

IE39
1/0
P34056861

Page 2
NRC Bulletin 90-01
May 29, 1990

Very truly yours,


Robert C. Mecredy
Division Manager
Nuclear Production

Subscribed and Sworn before me on

this 5th day of JUNE, 1990

LYNN L. HAUCK
Notary Public in the State of New York
MONROE COUNTY
Commission Expires Nov. 30, 1991

xc: U.S. Nuclear Regulatory Commission
Region 1
475 Allendale Road
King of Prussia, PA 19406

NRC Senior Resident Inspector - Ginna Station