

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8204160277 DOC. DATE: 82/04/13 NOTARIZED: NO DOCKET #
 FACIL: 50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244
 AUTH. NAME: MAIER, J.E. AUTHOR AFFILIATION: Rochester Gas & Electric Corp.
 RECIP. NAME: CRUTCHFIELD, D. RECIPIENT AFFILIATION: Operating Reactors Branch 5

SUBJECT: Forwards "Incident Evaluation: Ginna Steam Generator Tube Failure Incident, 820125." Rept on steam generator insp. evaluation & repair program will be submitted separately.

2222 SEE REPTS. # 8204160281
 DISTRIBUTION CODE: ~~ACR~~ COPIES RECEIVED: LTR 1 ENCL 40 SIZE: 1+200
 TITLE: ~~Steam Generator Feedwater Flow Instability (Water Hammer) (USI A-1)~~

NOTES: ~~NRR/DL/SEP 1-7~~

05000244

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID	CODE/NAME	LTTR	ENCL	ID	CODE/NAME	LTTR	ENCL
ORB #5	BC	01	5	5			
INTERNAL:	AEOD	12	1	1	ELD	14	1
	IE	06	1	1	NRR BURGER, L	13	1
	NRR/DL/ORAB	10	1	1	NRR/DSI/AEB		1
	NRR/DSI/ASB	09	1	1	NRR/DST/GIB	07	1
	REG FILE	04	1	1	RGN1		1
EXTERNAL:	ACRS	11	10	10	LPDR	03	1
	NRC PDR	02	1	1	NSIC	05	1
	NTIS		1	1			

Add: NRR / OHFS Delay
 NRR / DL DIR.
 NRR / DSI / RAB

TOTAL NUMBER OF COPIES REQUIRED: LTTR

35

35

31 ENCL

31

[illegible][illegible]

ORB#5 BC-5cys

Req File

I + E

NRR/RSB

NRR/ICSB

NRR/MTEB

NRR/CSB

NRR/MEB

NRR/PTRB

NRR/HFEB

NRR/DLB

I + E/EPLB

NRR/DL/ORAB

NRR/DSI/AEB

NRR/OSI/RAB

NRR/D/DL

NRR/D/DE

NRR/D/DHFS

IE D/DEP

NRR D/DST

DENTON/CASE

Speis, T.

Rubenstien


Johnston, W. V.

Knight, J. P.
Houston, R. W.

LPDR
NRC POR
NSIC

NTIS
ACRS-6cys


Dist. Per
James Lyons
E. Lyons
Pm.






ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

JOHN E. MAIER
Vice President




April 13, 1982

TELEPHONE
AREA CODE 716 546-2700



Director of Nuclear Reactor Regulation
Attention: Mr. Dennis M. Crutchfield, Chief
Operating Reactors Branch No. 5
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



Subject: Incident Evaluation
Steam Generator Tube Rupture Incident
R. E. Ginna Nuclear Power Plant
Docket No. 50-244

Dear Mr. Crutchfield:

At 9:25 a.m., on January 25, 1982, the Ginna B Steam Generator experienced a tube failure. The enclosed report provides an evaluation of the incident. A report on the steam generator inspection, evaluation, and repair program will be submitted separately. Forty copies of this letter and the enclosed report are provided.

Very truly yours,

John E. Maier
John E. Maier

Enclosure

2222

~~1012~~
51/40

~~Add. NRR/DHFS/DERY~~
~~NRR/DL/DNR~~
~~NRR/DSE/RAB~~

8204160277 820413
PDR ADCK 05000244
S PDR

