



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

JOHN E. MAIER
Vice President

TELEPHONE
AREA CODE 716 546-2700

April 26, 1982

Director of Nuclear Reactor Regulation
Attention: Mr. Dennis M. Crutchfield, Chief
Operating Reactors Branch No. 5
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: Steam Generator Evaluation
Steam Generator Tube Rupture Incident
R. E. Ginna Nuclear Power Plant
Docket No. 50-244



Dear Mr. Crutchfield:

At 9:25 a.m. on January 25, 1982, the Ginna B-Steam Generator experienced a tube failure. A report summarizing the sequence of events, operator actions, emergency procedures, equipment performance, radiological assessment, and recommendations related to the transient was submitted to the NRC by letter dated April 13, 1982. The enclosed report provides an evaluation of the steam generator and includes the results of inspections, a description of analysis and tests used to establish the tube failure mechanism, and a summary of repairs. Forty copies of this letter and the enclosed report are provided.

Very truly yours,

John E. Maier
John E. Maier

Enclosure

2222
[Signature]
1/40

8204280234

