

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SESSION NBR: 9002140238    DOC. DATE: 90/01/31    NOTARIZED: NO    DOCKET #  
 FACIL: 50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G    05000244  
 AUTH. NAME    AUTHOR AFFILIATION  
 MECREDY, R.C.    Rochester Gas & Electric Corp.  
 RECIP. NAME    RECIPIENT AFFILIATION  
 RUSSELL, W.T.    Region 1, Ofc of the Director

SUBJECT: Responds to violations noted in Insp Rept 50-244/89-15.

DISTRIBUTION CODE: IE01D    COPIES RECEIVED: LTR 1 ENCL 1    SIZE: 2  
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES: License Exp date in accordance with 10CFR2,2.109(9/19/72).    05000244

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD1-3 PD		1	1		JOHNSON, A		1	1
INTERNAL:	AEOD		1	1		AEOD/DEIIB		1	1
	AEOD/TPAD		1	1		DEDRO		1	1
	NRR SHANKMAN, S		1	1		NRR/DLPQ/LPEB10		1	1
	NRR/DOEA DIR 11		1	1		NRR/DREP/PEPB9D		1	1
	NRR/DREP/PRPB11		2	2		NRR/DRIS/DIR		1	1
	NRR/DST/DIR 8E2		1	1		NRR/PMAS/ILRB12		1	1
	NUDOCS-ABSTRACT		1	1		OE LIEBERMAN, J		1	1
	OGC/HDS2		1	1		<del>REG. FILE 02</del>		1	1
	RES MORISSEAU, D		1	1		RGN1 FILE 01		1	1
INTERNAL:	LPDR		1	1		NRC PDR		1	1
	NSIC		1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24





ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001



TELEPHONE  
AREA CODE 716 546-2700

January 31, 1990

Mr. William T. Russell  
Regional Administrator  
United States Nuclear Regulatory Commission  
Region I  
475 Allendale Road  
King of Prussia, PA 19406

Subject: Inspection Report 50-244/89-15  
R. E. Ginna Nuclear Power Plant  
Docket No. 50-244

Dear Mr. Russell:

This letter is to provide a response to the subject inspection regarding concerns in establishing proper system alignments and in the associated independent verification thereof.

In addition to the corrective actions associated with the Human Performance Evaluation System (HPES) Reports addressing the two incidents described in the inspection report, the following additional corrective actions are being taken:

1. The procedure addressing boric acid filter flush and isolation has been strengthened to provide tighter controls on isolation.
2. Through management directives, policies have been strengthened to insure complete on-shift attention to detail, improved in-depth communications and acknowledgement of responsibilities for return of equipment to service.
3. A general policy has been implemented that all miscellaneous vent and drain valves now are to be tagged, where practical, using the Station Holding Rules to control status during maintenance. The current Holding Policy requires independent verification to assure proper placement of isolation boundaries and subsequent removal thereof. This policy is formally being incorporated into our newly revised administrative holding procedure.
4. Operators have been made aware of the results of HPES 89-02 and HPES 89-03 involving the Human Performance Evaluations of the events.

9002140238 900131  
PDR ADCK 05000244  
Q PDC


IFD  
1/0  
Cut No  
BA0957184



5. To address the corrective action recommendation identified in the HPES Report regarding strengthening interdepartmental communications, a representative from Operations now participates in the daily maintenance planning meetings.
6. We are continuing to strengthen our station operating procedures through our normal periodic review. Also, as a result of a recent P&ID project, we are currently developing a plan to upgrade all applicable alignment procedures.
7. Subsequent to Inspection report 89-15, Administrative Procedure A-52.4 "Control of Limiting Conditions for Operation" has been changed to further delineate expected actions of personnel for return to service of previously inoperable equipment. Specific examples are utilized within the body of the procedure to reinforce these requirements.

Through these actions, RG&E will continue to ensure proper system alignments and independent verification thereof. In addition, a comprehensive in-depth review is currently in progress to assess both training and implementation effectiveness. Corrective actions resulting from this assessment will be documented in corrective Action Report #1990.

Very truly yours,



Robert C. Meckedy  
General Manager  
Nuclear Production.

xc: U.S. Nuclear Regulatory Commission (Original)  
Document Control desk  
Washington, D.C. 20555

NRC Senior Resident Inspector - Ginna Station

