

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NER:9308300074 DOC.DATE: 93/08/23 NOTARIZED: NO DOCKET #
FACIL:50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244
AUTH.NAME AUTHOR AFFILIATION
SECREDY,R.C. Rochester Gas & Electric Corp.
RECIP.NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Responds to NRC ltr re violations noted in insp rept
50-244/93-15 on 930719-23. Corrective actions: researched
packages & retrained involved security officer.

DISTRIBUTION CODE: IE04D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3
TITLE: Safeguards Inspection Rpt/NOV Response (50 DKT)-Publicly Available

NOTES: License Exp date in accordance with 10CFR2,2.109(9/19/72). 05000244

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD1-3 LA	1 0	PD1-3 PD	1 1
	JOHNSON,A	1 1		
INTERNAL:	AEOD/DOA	1 0	NRR/DRSS/PSGB9D	1 1
	NRR/PMAS/ILRB12	1 0	NUDOCS-ABSTRACT	1 1
	OE DIR	1 1	<u>REG-FILE</u> 02	1 1
	RGN1 FILE 01	1 1		
INTERNAL:	NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 12 ENCL 9



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001



TELEPHONE
AREA CODE 716 546-2700

August 23, 1993

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Inspection Report 50-244/93-15
Notice of Violation
R. E. Ginna Nuclear Power Plant
Docket No. 50-244
License No. DPR-18

Gentlemen:

Please find enclosed our reply to the Notice of Violation received as Appendix A to Inspection Report No. 50-244/93-15. The inspection was conducted by Messrs. A. Della Ratta and E. B. King July 19-23, 1993 at our facility.

Very truly yours,

Robert C. Mecredy
Robert C. Mecredy
Vice President
Ginna Nuclear Production

xc: U.S. Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, Pa. 19406

NRC Senior Resident Inspector
Ginna Station

W. K. Dillon

270043

9308300074 930823
PDR ADOCF 05000244
Q PDR



IE04
11

REPLY TO A NOTICE OF VIOLATION

Inspection Report 50-244/93-15
Rochester Gas and Electric Corporation
R. E. Ginna Nuclear Power Plant
Docket No. 50-244
License No. DPR-18

During an NRC inspection conducted July 19-23, 1993, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR 2, Appendix C, the violation is listed below:

The R. E. Ginna Nuclear Power Station Physical Security Plan, dated May 1, 1991, Revision A, Section 5.6.1, "Material and Package Search," states, in part, that most material and packages for delivery into the PA are brought to the off-loading portal. After being properly identified and authorization determined, the material and packages are appropriately searched for devices such as firearms, explosives and incendiary devices, consistent with radiation and practical considerations with five identified exceptions.

Contrary to the above, on July 22, 1993, the inspectors determined by observation that, packages, which were not excepted, were not being appropriately searched by the security officer at the off-loading dock, prior to granting the packages into the protected area. The security officer opened approximately twenty packages but failed to search the contents.

This is a Severity Level IV Violation (Supplement III).

We agree with this violation on the basis that on July 22, 1993, the security officer assigned to search packages at the off-loading portal opened approximately twenty packages and performed only a cursory inspection of the contents rather than performing a thorough search as required.

The violation was brought about as a result of confusion on the part of this security officer insofar as what constituted an appropriate search of the specific materials at hand.

The Security Training Supervisor implemented immediate corrective action by relieving the security officer of his duties and having the improperly searched packages searched by another security officer. The security officer involved was provided with hands-on retraining in package searching procedures.



Additional corrective steps taken to avoid future violations of the package search requirements are as follows: (1) A review of training methods and performance certification components was conducted by supervisory training personnel. Some minor revisions were made to clarify the search requirements. (2) All security personnel then received refresher training on package searches. (3) A Security Supervisor was assigned to observe all package deliveries at the off-loading portal for a period of thirty days to ensure that security personnel were performing package searches in accordance with procedures and instructions received in refresher training.

Full compliance with the NRC-approved R.E. Ginna Physical Security Plan was achieved immediately upon implementation of the corrective actions initiated by the Security Training Supervisor at the time of the violation.

