

PRIORITY 1

(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9511080187 DOC. DATE: 95/11/01 NOTARIZED: NO DOCKET #
FACIL: 50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244
AUTH. NAME AUTHOR AFFILIATION
MECREDY, R.C. Rochester Gas & Electric Corp.
RECIP. NAME RECIPIENT AFFILIATION
JOHNSON, A.R.

SUBJECT: Forwards missing table re ventilation sys testing & proposed
24 month refueling cycle intervals.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3
TITLE: OR Submittal: General Distribution

NOTES: License Exp date in accordance with 10CFR2,2.109(9/19/72). 05000244

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD1-1 LA	1 1	PD1-1 PD	1 1
	JOHNSON, A	1 1		
INTERNAL:	FILE CENTER 01	1 1	NRR/DE/EMCB	1 1
	NRR/DRCH/HICB	1 1	NRR/DSSA/SPLB	1 1
	NRR/DSSA/SRXB	1 1	NUDOCS-ABSTRACT	1 1
	OGC/HDS3	1 0		
EXTERNAL:	NOAC	1 1	NRC PDR	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL
DESK, ROOM OWFN 5D8 (415-2083) TO ELIMINATE YOUR NAME FROM
DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 12 ENCL 11

MA4



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001



AREA CODE 716 546-2700

ROBERT C. MECREDY
Vice President
Nuclear Operations

November 1, 1995

U.S. Nuclear Regulatory Commission
Document Control Desk
Attention: Mr. Allen R. Johnson
Project Directorate I-1
Washington, D.C. 20555


Subject: Conversion to Improved Technical Specifications
24 Month Cycle Evaluation, Ventilation Testing Requirements (TAC No. 92965)
Rochester Gas & Electric Corporation
R.E. Ginna Nuclear Power Plant
Docket No. 50-244

Reference: (a) Letter from R.C. Mecredy, RG&E, to A.R. Johnson, NRC, Subject:
*Conversion to Improved Technical Specifications, 24 Month Cycle
Evaluation, Ventilation Testing Requirements (TAC No. 92965)*, dated
October 18, 1995.

Dear Mr. Johnson,

By Reference (a), RG&E had provided the NRC with responses to two conference calls related to ventilation system testing and proposed 24 month refueling cycle intervals. A table, as referenced within this letter, was inadvertently not provided. Therefore, please find the missing table attached.

Very truly yours,


Robert C. Mecredy

MDF\770a

080030

attachment

9511080187 951101
PDR ADCK 05000244
PDR

A001
11

xc: U.S. Nuclear Regulatory Commission
Mr. Allen R. Johnson (Mail Stop 14B2)
PWR Project Directorate I-1
Washington, D.C. 20555

U.S. Nuclear Regulatory Commission (w/o attachment)
Mr. Carl Schulten (Mail Stop 011E22)
Office of Technical Specifications Branch
Washington, D.C. 20555

U.S. Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406

Ginna Senior Resident Inspector

System	Tests Performed / Frequency	Failures Since 1980
Containment Post-Accident Charcoal System	<ol style="list-style-type: none"> 1. Annual testing of charcoal filters (procedure PT-47.11). 2. Monthly and quarterly testing of fans and dampers (procedures PT-2.3.1M). 3. Quarterly damper stroke testing (procedure PT-2.3.1Q). 	No failures. However, charcoal filters have been replaced following expiration of filter media (i.e., > 720 hours of operation).
Control Room Emergency Air Treatment System (CREATS)	<ol style="list-style-type: none"> 1. Monthly test of radiation and toxic gas monitors and actuation of system (procedure PT-17.4). 2. Annual testing of charcoal and HEPA filters (procedure PT-47.3). 	No failures. However, charcoal filters have been replaced following contamination events (smoke) and expiration of filter media (i.e., > 720 hours of operation).
Spent Fuel Pool Charcoal Adsorber System ⁽¹⁾	<ol style="list-style-type: none"> 1. Annual testing of charcoal filters (procedure PT-47.10). 	No failures. However, charcoal filters have been replaced following contamination events (painting) and expiration of filter media (i.e., > 720 hours of operation).
Containment Recirculation Fan Coolers	<ol style="list-style-type: none"> 1. Annual testing of HEPA filters (procedure PT-47.5). 2. Monthly testing of fans and dampers (procedure PT-2.3.1M). 3. Quarterly damper stroke testing (procedure PT-2.3.1Q). 	No failures. However, HEPA filters have been replaced following expiration of filter media (i.e., > 720 hours of operation).

Notes:

1. No actuation logic associated with this ventilation system.

