

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9812070104 DOC. DATE: 98/11/24 NOTARIZED: NO DOCKET #
 FACIL: 50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244
 AUTH. NAME AUTHOR AFFILIATION
 MECREDY, R.C. Rochester Gas & Electric Corp.
 RECIP. NAME RECIPIENT AFFILIATION
 VISSING, G.S.

SUBJECT: Forwards LER 98-003-01 re event or condition that resulted in manual or automatic actuation of ESF, including RPS, per 10CFR50.73. Rev 1 addresses root cause of actuations of CR emergency air treatment sys.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 9
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: License Exp date in accordance with 10CFR2, 2.109 (9/19/72). 05000244

RECIPIENT ID CODE/NAME	COPIES	LTTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTTR	ENCL
PD1-1 PD	1		1	VISSING, G.	1		1
INTERNAL: AEOD/SPD/RAB	2		2	AEOD/SPD/RRAB	1		1
FILE CENTER	1		1	NRR/DE/ECGB	1		1
NRR/DE/EELB	1		1	NRR/DE/EMEB	1		1
NRR/DRCH/HICB	1		1	NRR/DRCH/HOHB	1		1
NRR/DRCH/HQMB	1		1	NRR/DRPM/PECB	1		1
NRR/DSSA/SPLB	1		1	RES/DET/EIB	1		1
RGN1 FILE 01	1		1				
EXTERNAL: L ST LOBBY WARD	1		1	LITCO BRYCE, J H	1		1
NOAC POORE, W.	1		1	NOAC QUEENER, DS	1		1
NRC PDR	1		1	NUDOCS FULL TXT	1		1

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LIST:
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
 DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 22



ROCHESTER GAS AND ELECTRIC CORPORATION - 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001
AREA CODE 716-546-2700

ROBERT C. MECREDY
Vice President
Nuclear Operations

November 24, 1998



U.S. Nuclear Regulatory Commission
Document Control Desk
Attn: Guy S. Vissing
Project Directorate I-1
Washington, D.C. 20555


Subject: LER 1998-003, Revision 1, Radon Build-up During Temperature Inversion
Results in Actuations of Control Room Emergency Air Treatment System
R.E. Ginna Nuclear Power Plant
Docket No. 50-244

Dear Mr. Vissing:

In accordance with 10 CFR 50.73, Licensee Event Report System, item (a) (2) (iv), which requires a report of, "any event or condition that resulted in manual or automatic actuation of any Engineered Safety Feature (ESF), including the Reactor Protection System (RPS)", the attached Licensee Event Report LER 1998-003 (Revision 1) is hereby submitted. Revision 1 addresses the root cause of actuations of the Control Room Emergency Air Treatment System.

These events have in no way affected the public's health and safety.

Very truly yours,


Robert C. Mecredy

xc: Mr. Guy S. Vissing (Mail Stop 14B2)
Project Directorate I-1
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

U.S. NRC Ginna Senior Resident Inspector

9812070104 981124
PDR ADOCK 05000244
S PDR

Je 22

