



Washington Public Power Supply System  
A JOINT OPERATING AGENCY

P. O. Box 968

3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352

PHONE (509) 375-5000

February 22, 1979  
G02-79-27

Nuclear Regulatory Commission  
Region V  
Office of Inspection & Enforcement  
Suite 202, Walnut Creek Plaza  
1900 N. California Boulevard  
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken, Director

Subject: WPPSS NUCLEAR PROJECT NO. 2  
DOCKET NUMBER 50-397, CPPR-93  
REPORTABLE DEFICIENCY - 10CFR50.55(e)



Dear Mr. Engelken:

In accordance with the provisions of 10CFR50.55(e), your staff was informed by telephone on January 25, 1979, of a reportable deficiency involving a primary containment penetration weld design error which could result in the possible violation of primary containment.

Attached is our report on this deficiency.

Please contact us if you have additional questions.

Very truly yours,

*D. L. Renberger*

D. L. RENBERGER  
Assistant Director  
Technology

DLR:FEM:cph

attachment: as stated

cc w/att: JJ Verderber - B&R  
D. Roe - BPA  
E. Volgenau - Director of Inspection  
and Enforcement, NRC  
WNP-2 Files

790322 0031

79-12



1999