

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7904270375 DOC. DATE: 79/04/17 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS NUCLEAR PROJECT, UNIT 2, WASHINGTON PUBLIC POWE. 05000397
 AUTH. NAME: RENBERGER, D.L. AUTHOR AFFILIATION: WASHINGTON PUBLIC POWER SUPPLY SYSTEM
 RECIP. NAME: ENGELKEN, R.H. RECIPIENT AFFILIATION: REGION 5, SAN FRANCISCO, OFFICE OF THE DIRECTOR

SUBJECT: FORWARDS REPORTABLE DEFICIENCY AS REPORTED BY 790319 TELCON,
 RE DEFECTIVE TERMINAL LUGS ON ELECTRICAL CONTAINMENT
 PENETRATIONS X-105 A,B,C & D.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 171
 TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).

NOTES: BILL PATON OELD ICY ER AMDTS. PM-2 CYS ALL MATL!


	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID	CODE/NAME	LTTR	ENCL		ID	CODE/NAME	LTTR	ENCL
ACTION:	14	PM M LYNCH	1	1	15	BC LWR #4	1	1	
	20	LA LWR #4	1	1		21	AD VASSALLO	1	1
INTERNAL:	01	REG FILE	1	1	02	NRC PDR	1	1	
	05	I&E	2	2	07	EDO & STAFF	1	1	
	08	MPA	1	1	09	DEPY DIR DPM	1	1	
	10	GAB	1	1	11	STANDROS DEV	1	1	
	12	JORDAN, E/IE	1	1	13	FIELD COOR/IE	1	1	
	16	AD FOR ENGR	1	1	17	AD PLANT SYS	1	1	
	17	AD REAC SFTY	1	1	19	AD SYS/PROJ	1	1	
	22	DIR DPM	1	1	23	OELD	1	1	
EXTERNAL:	03	LPDR	1	1	04	NSIC	1	1	
	24	ACRS	16	16					

TOTAL NUMBER OF COPIES REQUIRED: LTTR 39 ENCL 39

MAY 1979

MA 1

BD



Washington Public Power Supply System
A JOINT OPERATING AGENCY

P. O. Box 968 3000 GEO. WASHINGTON WAY RICHLAND, WASHINGTON 99352 PHONE (509) 375-5000

April 17, 1979
G02-79-68

Nuclear Regulatory Commission
Region V
Office of Inspection and Enforcement
Suite 202, Walnut Creek Plaza
1900 N. California Boulevard
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken, Director

Subject: WPPSS NUCLEAR PROJECT NO. 2
DOCKET NUMBER 50-397, CPPR-93
REPORTABLE DEFICIENCY, 10CFR50.55(e)

Dear Mr. Engelken:

In accordance with the provisions of 10CFR50.55(e), your staff was informed by telephone on March 19, 1979, of a reportable deficiency involving defective termination lugs on Electrical Containment Penetrations X-105 A, B, C, and D.

Attached is our report on this deficiency. Please contact us if you have any additional questions.

Very truly yours,

D. L. RENBERGER
Assistant Director
Technology

DLR/DCT/ln

Attachment: As stated

cc w/att: C Bryant - BPA
JJ Verderber - B&R
JG Davis - Director of Inspection
& Enforcement, NRC,
Washington, D.C.
WNP-2 Files

Boia
5/1

7904270 375

