

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:7905010478 DOC.DATE: 79/04/23 NOTARIZED: NO DOCKET #
 FACIL:50-397 WPPSS NUCLEAR PROJECT, UNIT 2, WASHINGTON PUBLIC POWE 05000397
 AUTH.NAME AUTHOR AFFILIATION
 RENBERGER,D.L. WASHINGTON PUBLIC POWER SUPPLY SYSTEM
 RECIP.NAME RECIPIENT AFFILIATION
 ENGELKEN,R.H. REGION 5, SAN FRANCISCO, OFFICE OF THE DIRECTOR

SUBJECT: CLARIFIES UTIL POSITION RE POTENTIALLY REPORTABLE DEFICIENCY
 ON 790223 RE ESSENTIAL FAN BEING FED BY NON-ESSENTIAL MOTOR
 CONTROL CENTER.IT IS NOT YET DETERMINED WHETHER THIS IS
 REPORTABLE.

DISTRIBUTION CODE: 8019S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 3
 TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).


NOTES: BILL PATON OELD ICY ER AMDTS PM-2CYS ALL MATL.

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	14 PM M LYNCH	1 1	15 BC LWR #4	1 1
	20 LA LWR #4	1 1	21 AD VASSALLO	1 1
INTERNAL:	01 <u>REC FILE</u>	1 1	02 NRC PDR	1 1
	05 I&E	2 2	07 EDO & STAFF	1 1
	08 MPA	1 1	09 DEPY DIR DPM	1 1
	10 QAB	1 1	11 STANDRDS DEV	1 1
	12 JORDAN,E/IE	1 1	13 FIELD COOR/IE	1 1
	16 AD FOR ENGR	1 1	17 AD PLANT SYS	1 1
	17 AD REAC SFTY	1 1	19 AD SYS/PROJ	1 1
	22 DIR DPM	1 1	23 OELD	1 1
EXTERNAL:	03 LPDR	1 1	04 NSIC	1 1
	24 ACRS	16 16		

MAY 2 1979

MA 4
 60

TOTAL NUMBER OF COPIES REQUIRED: LTTR 39 ENCL 39



Washington Public Power Supply System
A JOINT OPERATING AGENCY

P. O. Box 968 3000 GEO. WASHINGTON WAY RICHLAND, WASHINGTON 99352 PHONE (509) 375-3000

April 23, 1979
G02-79-77

Nuclear Regulatory Commission
Region V
Office of Inspection & Enforcement
Suite 202, Walnut Creek Plaza
1900 N. California Boulevard
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken, Director

Subject: WPPSS NUCLEAR PROJECT NO. 2
DOCKET NUMBER 50-397, CPPR-93
POTENTIAL REPORTABLE DEFICIENCY
10CFR50.55(e)

Dear Mr. Engelken:

Your staff was notified of a potentially reportable 10CFR50.55(e) deficiency on February 23, 1979, regarding an essential fan, RRA-FN-12, being fed by a non-essential motor control center, MCC 7C-A.

Mr. T. Bishop of your staff, on March 29, 1979, requested the status of the WPPSS reportable deficiency report which is required within thirty (30) days, the identification of a 10CFR50.55(e) reportable condition. It is apparent that a misunderstanding has occurred. WPPSS did not report this condition as a reportable deficiency to NRC under the provisions of 10CFR50.55(e). The telecon of February 23, 1979 was a communique to Region V identifying a potentially reportable condition.

As of this date, an engineering directive has been issued which will assure that when the installation is made, the essential fan, RRA-FN-12, will be fed by an essential motor control center Mcc 7B. The evaluation of this potentially reportable condition has not been completed.

7905010478

Bol
5/1

SECRET

Your staff will be notified if the evaluation concludes this condition is reportable under the provision of 10CFR50.55(e).

Attached is a copy of the Record of Telephone Conversation of February 23, 1979.

Please contact us if you have additional questions.

Very truly yours,

D L Renberger

D. L. RENBERGER
Assistant Director
Technology

DLR/RPS/ln

Attachment: As stated

cc w/att: C Bryant - BPA
JJ Verderber - B&R
E Volgenau - Director of Inspection
and Enforcement, NRC,
Washington, D.C.
WNP-2 Files

() YES
(X) NO

Distribution: MJ Parise AM Sastry
CC:File RP Sabol