

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SESSION NBR: 7905090069 DOC. DATE: 79/04/30 NOTARIZED NO DOCKET #
 ACIL: 50-397 WPPSS NUCLEAR PROJECT, UNIT 2, WASHINGTON PUBLIC POWER 05000397
 AUTH. NAME AUTHOR AFFILIATION
 ENBERGER, D.L. WASHINGTON PUBLIC POWER SUPPLY SYSTEM
 RECIP. NAME RECIPIENT AFFILIATION
 ENGELKEN, R.H. REGION 5, SAN FRANCISCO, OFFICE OF THE DIRECTOR

SUBJECT: FORWARDS REPT ON DEFICIENT BASIC INFLOW VALVES USED IN
 STANDBY GAS TREATMENT SYS.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 7x11
 TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).

NOTES: BILL PATON OELD TICY ER AMDS PM - 2 CYS ALL MATL


	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL			RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
ION:	14 PM M LYNCH	1	1		15 BC LWR #4	1	1
	20 LA LWR #4	1	1		21 AD UASSALLO	1	1
ERNAL:	01 REG FILE	1	1		02 NRC PDR	1	1
	05 I&E	2	2		07 EDO & STAFF	1	1
	08 MPA	1	1		09 DEPY DIR DPM	1	1
	10 QAB	1	1		11 STANDRDS DEV	1	1
	12 JORDAN, E/IE	1	1		13 FIELD COOR/IE	1	1
	16 AD FOR ENGR	1	1		17 AD PLANT SYS	1	1
	17 AD REAC SFTY	1	1		19 AD SYS/PROJ	1	1
	22 DIR DPM	1	1		23 OELD	1	1
ERNAL:	03 LPDR	1	1		04 NSIC	1	1
	24 ACRS	16	16				

MAY 10 1979

TOTAL NUMBER OF COPIES REQUIRED: LTTR 39 ENCL 39

MA 4

60



Washington Public Power Supply System
A JOINT OPERATING AGENCY

P. O. Box 968

3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352

PHONE (509) 375-5000

April 30, 1979
G02-79-80

Nuclear Regulatory Commission
Region V
Office of Inspection & Enforcement
Suite 202, Walnut Creek Plaza
1900 N. California Boulevard
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken, Director

Subject: WPPSS NUCLEAR PROJECT NO. 2
DOCKET NUMBER 50-397, CPPR-93
REPORTABLE DEFICIENCY - 10CFR50.55(e)

Dear Mr. Engelken:

In accordance with the provisions of 10CFR50.55(e), your staff was informed by telephone on October 31, 1978, of a potentially reportable condition involving possible failure of Basic In Flow (BIF) valves utilized in the Standby Gas Treatment System.

Attached herewith is our report on the deficiency. The report was not previously issued because it was erroneously considered unnecessary to report this condition under the provision of 10CFR50.55(e), in as much as NRC was officially informed under the provision of 10CFR Part 21 by BIF on October 18, 1978.

Please contact us if you have additional questions.

Very truly yours,

D. L. RENBERGER
Assistant Director
Technology

DLR/RPS:ln

Attachment: As stated

cc w/att: JJ Verderber - B&R
C Bryant - BPA

(3) JG Davis - (Acting) Director of Inspection
and Enforcement, NRC, Washington, D.C.

WNP-2 Files
RE Rayner, BIF

7905090069