

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7912120413 DOC. DATE: 79/11/30 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Power 05000397
 AUTH. NAME: AUTHOR AFFILIATION
 RENBERGER, D.L. Washington Public Power Supply System
 RECIP. NAME: RECIPIENT AFFILIATION
 ENGELKEN, R.H. Region 5, San Francisco, Office of the Director

SUBJECT: Forwards final deficiency report re ECCS pump room flooding.

DISTRIBUTION CODE: B019B COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 141
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: PM: 2 CYS ALL NHTC

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	14 PM P. LYNCH	1	15 BC LWR #4	1
	20 LA LWR #4	1	21 AD LWR	1
INTERNAL:	01 REG FILE	1	02 NRC PDR	1
	05 I&E	2	07 EDO & STAFF	1
	08 MPA	1	09 DEPY DIR DPM	1
	10 QAB	1	11 STANDRDS DEV	1
	12 JORDAN, E/IE	1	13 FIELD. COOR/IE	1
	16 AD FOR ENGR	1	17 AD PLANT SYS	1
	17 AD REAC SFTY	1	22 DIR DPM	1
	23 OELD	1	AD/SITE TECH	1
	DIRECTOR DSE	1	GEOSCIENCES BR	1
	I&C SYS BR	1	MATL ENG BR	1
	MECH ENG BR	1	POWER SYS BR	1
	S HANAUER	1	STRUCT ENG BR	1
EXTERNAL:	03 LPDR	1	04 NSIC	1
	24 ACRS	16		

LTR:

0100RE

EPB #2

J. NORRIS

EPB #2

DEC 12 1979

52


TOTAL NUMBER OF COPIES REQUIRED: LTR

ENCL

67

MA
1

Page 100



Washington Public Power Supply System
A JOINT OPERATING AGENCY

P. O. Box 968

3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352

PHONE (509) 375-5000

November 30, 1979
G02-79-212

Nuclear Regulatory Commission
Region V
Office of Inspection and Enforcement
Suite 202, Walnut Creek Plaza
1900 North California Boulevard
Walnut Creek, CA 94596

Attention: Mr. R. H. Engelken, Director

Subject: WPPSS NUCLEAR PROJECT NO. 2
DOCKET NUMBER 50-397
REPORTABLE DEFICIENCY - 10CFR50.55(e)

References: Letter G02-79-191 from D. L. Renberger to R. H. Engelken
dated October 18, 1979, same subject

Dear Mr. Engelken:

The referenced letter documented a reportable condition in accordance with the provisions of 10CFR50.55(e) involving the WNP-2 spent fuel pool cooling system. The letter also included an interim report of the deficiency.

The final report of action being taken to correct this condition is attached.

Please contact us if you have additional questions.

Very truly yours,

D. L. RENBERGER
Assistant Director Technology

DLR:TRM:cd

attachment: as stated

cc: JM Blas - B&R w/att
JJ Verderber - B&R w/att
RE Snaith - B&R w/att
JR Lewis - BPA w/att
JG Davis, Director, NRC, Washington, D.C., w/att
RC Root - B&R Site w/att
MJ Parise - B&R Site w/att
WNP-2 files w/att
GT Harper - B&R Site w/att

3019
SE

2012/12/0 4/3

S

