

RECEIVED  
NRC

## Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000  
1984 JUL 30 PM 2:35

Docket No. 50-397

July 26, 1984

REGION VI&E

Mr. T.W. Bishop, Director  
Division of Reactor Safety and Projects  
U.S. Nuclear Regulatory Commission  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596

8408090262 840726  
PDR ADCK 05000397  
P PDR

IE FILE COPY

Attention: Mr. A. L. Hon, Reactor Inspector

Subject: NUCLEAR PLANT NO. 2  
LICENSE NO. NPF-21  
NRC INSPECTION  
WEEK JULY 16, 1984

Reference: Letter G02-83-908 dated 10/11/83 from G.C. Sorensen (SS)  
to A. Schwencer (NRC); Procedure Generation Package for WNP-2

At the Management Meeting for the subject inspection, Mr. A.L. Hon requested a copy of the BWR Owners' Group guidelines that were used to generate Emergency Operating Procedures. The guidelines will be used for additional verification of WNP-2's response to TMI Item I.C.1, Development of Procedures for Transients and Accidents.

Please find attached a copy of the referenced letter which includes the guidelines used for these procedures.

Should you have any questions concerning our response, please do not hesitate to call me.

*G. C. Sorensen*  
G. C. Sorensen  
Manager, Regulatory Programs

RCM:jdb

Attachments: As stated

1/0  
IE-28