

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8809220239 DOC. DATE: 88/09/19 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH. NAME AUTHOR AFFILIATION
 SORESENSEN, G.C. Washington Public Power Supply System
 RECIP. NAME RECIPIENT AFFILIATION

Document Control Branch (Document Control Desk) *566*
1287

SUBJECT: Forwards "Inservice Insp Summary Rept for Refueling Outage
 RF88A," Spring 1988.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 5 SIZE: 1+370
 TITLE: OR Submittal: Inservice Inspection/Testing/Relief from ASME Code

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID	CODE/NAME	LTTR	ENCL		ID	CODE/NAME	LTTR	ENCL
	PD5	LA	1	0		PD5	PD	5	5
		SAMWORTH, R	1	1					
INTERNAL:	ACRS		6	6		AEOD/DOA		1	1
	AEOD/DSP/TPAB		1	1		ARM/DAF/LFMB		1	0
	NRR/DEST/MEB 9H		1	1		NRR/DEST/MTB 9H		1	1
	NUDOCS-ABSTRACT		1	1		OGC/HDS2		1	0
	<u>REG FILE</u> 01		1	1		RES/DSIR/EIB		1	1
EXTERNAL:	EG&G ROCKHOLD, H		1	1		LPDR		1	1
	NL 007 HEMMING		1	1		NRC PDR		1	1
	NSIC		1	1					

TOTAL NUMBER OF COPIES REQUIRED: LTTR 27 ENCL 19

19
M/A 2

R
I
D
S
/
A
D
D
S
/
A
D
D
S
/
A
D
D
S

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

G02-88-200
September 19, 1988

Docket No. 50-397

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-137
Washington, D.C. 20555

Gentlemen:

Subject: NUCLEAR PLANT NO. 2
OPERATING LICENSE NPF-21
INSERVICE INSPECTION SUMMARY REPORT
NIS-1, NIS-2, OWNER'S REPORTS

Reference: Letter, G02-87-246, GC Sorensen (SS) to NRC,
same subject, dated September 17, 1987

In accordance with the requirements of 10CFR 55a(g), and IWA-6230 of ASME Section XI, as previously agreed, the Supply System hereby submits five (5) copies of the WNP-2 Inservice Inspection (ISI) Summary Report for the Spring 1988 refueling outage. Included in the Summary Report are the NIS-1 Owner's Data Report for inservice inspections performed during the Spring 1988 refueling outage, and NIS-2 Owner's Reports on repair or replacement completed since the filing of the last ISI Summary Report (see reference).

Very truly yours,


G. C. Sorensen, Manager
Regulatory Programs

HLA/bk

cc: JB Martin - NRC RV
NS Reynolds - BCP&R
RB Samworth - NRC
DL Williams - BPA/399
NRC Site Inspector - 901A

8809220239 880919
PDR ADOCK 05000397
Q PDC

A047
1/5