

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

| | | | |
|--------------------------|---|---------------|----------|
| ACCESSION NBR:9808030029 | DOC.DATE: 98/07/23 | NOTARIZED: NO | DOCKET # |
| FACIL:50-397 | WPPSS Nuclear Project, Unit 2, Washington Public Powe | | 05000397 |
| AUTH.NAME | AUTHOR AFFILIATION | | |
| BEMIS, P.R. | Washington Public Power Supply System | | |
| RECIP.NAME | RECIPIENT AFFILIATION | | |
| | Records Management Branch (Document Control Desk) | | |

SUBJECT: Forwards LER 98-006-01, discussing results of root cause analysis & addl corrective actions taken to rectify deficiencies in WNP, Unit 2, 10CRF, App R high impedance fault calculations.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

| RECIPIENT | | COPIES | | RECIPIENT | | COPIES | |
|---------------------------|-----------|------------------------|-----------|--------------|-----------|--------------|-----------|
| ID CODE/NAME | LTTR ENCL | ID CODE/NAME | LTTR ENCL | ID CODE/NAME | LTTR ENCL | ID CODE/NAME | LTTR ENCL |
| PD4-2 PD | 1 1 | POSLUSNY, C | 1 1 | | | | |
| INTERNAL: ACRS | 1 1 | AEOD/SPD/RAB | 2 2 | | | | |
| AEOD/SPD/RRAB | 1 1 | FILE CENTER | 1 1 | | | | |
| NRR/DE/ECGB | 1 1 | NRR/DE/EELB | 1 1 | | | | |
| NRR/DE/EMEB | 1 1 | NRR/DRCH/HICB | 1 1 | | | | |
| NRR/DRCH/HOHB | 1 1 | NRR/DRCH/HQMB | 1 1 | | | | |
| NRR/DRPM/PECB | 1 1 | NRR/DSSA/SPLB | 1 1 | | | | |
| RES/DET/EIB | 1 1 | RGN4 FILE 01 | 1 1 | | | | |
| EXTERNAL: L ST LOBBY WARD | 1 1 | LITCO BRYCE, J H | 1 1 | | | | |
| NOAC POORE, W. | 1 1 | NOAC QUEENER, DS | 1 1 | | | | |
| NRC PDR | 1 1 | NUDOCS FULL TXT | 1 1 | | | | |

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • Richland, Washington 99352-0968

July 23, 1998
GO2-98-133

Docket No. 50-397

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555


Gentlemen:

Subject: **WNP-2, OPERATING LICENSE NPF-21
LICENSEE EVENT REPORT NO. 98-006-01**

Transmitted herewith is Licensee Event Report No. 98-006-01 for WNP-2. This supplemental report discusses the results of the root cause analysis and additional corrective actions taken to rectify deficiencies in the WNP-2 10 CFR 50 Appendix R high impedance fault calculations. This report is submitted pursuant to 10 CFR 50.73 and discusses the items of reportability, corrective action taken, and action to preclude recurrence.

Should you have any questions or desire additional information pertaining to this letter, please call me or Mr. P. J. Inserra at (509) 377-4147.

Respectfully,



P/R. Bemis
Vice President, Nuclear Operations
Mail Drop PE23

Attachment

cc: EW Merschoff - NRC RIV
DF Kirsch - NRC, WCFO
C Poslusny, Jr. -NRR
INPO Records Center - Atlanta, GA

NRC Senior Resident Inspector - MD927N (2)
DL Williams - BPA, 1399
PD Robinson - Winston & Strawn

9808030029 980723
PDR ADOCK 05000397
S PDR

11
Teiz

