

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9909090208 DOC.DATE: 99/08/30 NOTARIZED: NO DOCKET #
 FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH.NAME AUTHOR AFFILIATION
 COLEMAN,D.W. Washington Public Power Supply System
 RECIP.NAME RECIPIENT AFFILIATION
 Records Management Branch (Document Control Desk)

SUBJECT: Provides correct page from license NPF-21 marked to show
 rev addressed in 990729 application for amend,which included
 page that was inadvertently included as attachment 4.Replace
 attachment 4 with attached page & disregard attachment 5.

DISTRIBUTION CODE: A001D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 3
 TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
	LPD4-2 LA	1	1	CUSHING,J	1	1
	SC	1	1			
INTERNAL:	ACRS	1	1	FILE CENTER 03	1	1
	NRR/DSSA/SPLB	1	1	NRR/DSSA/SRXB	1	1
	NUDOCS-ABSTRACT	1	1	OGC/RP.	1	0
EXTERNAL:	NOAC	1	1	NRC PDR	1	1

RECEIVED

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
 DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 11 ENCL 10

AA2

ENERGY
NORTHWEST

P.O. Box 968 ■ Richland, Washington 99352-0968

August 30, 1999
GO2-99-165

Docket No. 50-397

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Gentlemen:

**Subject: WNP-2, OPERATING LICENSE NPF-21
REQUEST FOR AMENDMENT, POST-ACCIDENT NEUTRON FLUX
MONITORING, LICENSE CONDITION 2.C.(16), ATTACHMENT 2
ITEM 3(b)**

Reference: Letter dated July 29, 1999, RL Webring (Energy Northwest) to NRC, "Request for Amendment, Post-Accident Neutron Flux Monitoring, License Condition 2.C.(16), Attachment 2, Item 3(b)"

The purpose of this letter is to provide the correct page from Operating License NPF-21 marked to show the revision addressed in the reference letter. The reference letter included a page that was inadvertently included as Attachment 4. Please replace Attachment 4 noted in the reference letter, with the attached page. In addition, please disregard Attachment 5, "Revised Operating License Page" included in the reference letter as it has been determined that it is not necessary.

Should you have any questions or require additional information pertaining to this letter, please contact PJ Inserra at (509) 377-4147.

Respectfully,

D. W. Coleman

DW Coleman
Manager, Regulatory Affairs
Mail Drop PE20

Attachment

cc: EW Merschoff - NRC - RIV
JS Cushing - NRC - NRR
TC Poindexter - Winston & Strawn

NRC Sr. Resident Inspector - 927N
DL Williams - BPA/1399

9909090208 990830
PDR ADDCK 05000397
P PDR

1/1

A001

1944 TV

REQUEST FOR AMENDMENT, POST-ACCIDENT NEUTRON FLUX MONITORING,
LICENSE CONDITION 2.C.(16), ATTACHMENT 2, ITEM 3(b)

Attachment 1

Operating License Marked-Up page

-2-

3. Regulatory Guide 1.97, Revision 2 Compliance

- (a) The licensee shall implement (installation or upgrade) requirements of Regulatory Guide 1.97, Revision 2 with the exception of items (b) and (c) below prior to startup following the first refueling outage.

~~DELETED~~

- ~~(b) The licensee shall implement (installation or upgrade) requirements of Regulatory Guide 1.97, Revision 2, for flux monitoring prior to startup following the fourth refueling outage.~~

- (c) The licensee shall implement (install and have operational) a wide range suppression pool level monitoring system which satisfies the Category 1 equipment specifications in accordance with Regulatory Guide 1.97, Revision 2, prior to startup following the second refueling outage.

4. Upgrade Emergency Operating Procedures (EOPs)

The licensee shall provide within two(2) months after the issuance of this operating license, an addendum to the Procedures Generation Package describing the function and task analysis as identified in Supplement 1 to NUREG-0737.

5. Emergency Response Facilities

The licensee shall have fully functional emergency response facilities (Technical Support Center, Operational Support Center, and Emergency Operations Facility) prior to exceeding five (5) percent of rated power.

