

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9203260145 DOC. DATE: 92/03/18 NOTARIZED: NO DOCKET #  
 CIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397  
 AUTH. NAME AUTHOR AFFILIATION  
 GRUMME, L.L. Washington Public Power Supply System  
 RECIP. NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Suppls 920213 response to violations noted in Insp Rept  
 50-397/91-44. Corrective actions: pipe supports restored  
 to configuration on drawings & missing pipe support nuts  
 replaced & loose items tightened.

DISTRIBUTION CODE: IE14D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: Enforcement Action Non-2.790-Licensee Response

### NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES		
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL	
	PD5 LA		1	1		PD5 PD		1	1	
	ENG, P.L.		1	1						
INTERNAL:	AEOD/DOA		1	1		AEOD/DSP/TPAB		1	1	
	DEDRO		1	1		NRR/DOEA/OEAB11		1	1	
	NRR/PMAS/ILRB12		1	1		NUDOCS-ABSTRACT		1	1	
	OE DIR		1	1		OE FILE 01		1	1	
	REG FILE 02		1	1		RGN5 FILE 03		1	1	
EXTERNAL:	NRC PDR		1	1		NSIC		1	1	

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 15 ENCL 15



6



WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352-0968 • (509) 372-5000

March 18, 1992  
G02-92-066

Docket No. 50-397


U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Station P1-137  
Washington, D. C. 20555

Subject: WNP-2, OPERATING LICENSE NO. NPF-21  
NRC INSPECTION REPORT 91-44  
SUPPLEMENTAL RESPONSE TO NOTICE OF VIOLATIONS AND  
CIVIL PENALTY

Reference: Letter, G02-92-056, dated February 13, 1992, GC Sorensen (SS) to  
Document Control Desk (NRC), "NRC Inspection Report 91-44 Response  
to Notice of Violation"

The response to Violation B.1 in the reference discusses a review that was performed to resolve identified pipe support problems. This item is documented on pages five through eight of Appendix A to the referenced letter. This letter responds to an inquiry by the WNP-2 Resident Inspector regarding the actions taken to correct the pipe support deficiencies. Corrective action was taken to restore the pipe supports to the configuration on the drawings. Missing pipe support nuts were replaced and loose items were tightened. A check was made of all fasteners on the recombiner skids. In addition, torque paint was applied to fastener nuts to assist in future inspections.

Sincerely,

  
L. L. Grumme, Acting Director  
Licensing & Assurance

CLF/bk

cc: JB Martin - NRC RV  
NS Reynolds - Winston & Strawn  
WM Dean - NRR  
DL Williams - BPA/399  
NRC Site Inspector - 901A

9203260145 920318  
PDR ADCK 05000397  
G PDR

*JEH 1/0*

