

## ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9208060167      DOC. DATE: 92/07/30      NOTARIZED: NO      DOCKET #  
FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe      05000397  
AUTH. NAME      AUTHOR AFFILIATION  
SORENSEN, G.C.      Washington Public Power Supply System  
RECIP. NAME      RECIPIENT AFFILIATION  
MARTIN, J.B.      Region 5 (Post 820201)

SUBJECT: Forwards "Radiological Environ Monitoring Special Rept for  
Jul 1992."

DISTRIBUTION CODE: IE25D      COPIES RECEIVED: LTR 1 ENCL 1      SIZE: 1+44  
TITLE: Environmental Monitoring Rept (per Tech Specs)

NOTES: *See Enviro Report*

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	3 3	PD5 PD	1 1
	DEAN, W.	1 1		
INTERNAL:	ACRS	1 1	NRR/DREP/PRPB11	2 2
	<u>REG FILE</u> 01	1 1	RGN5 DRSS/RPB	1 1
	RGN5 FILE 02	1 1		
EXTERNAL:	EG&G SIMPSON, F	2 2	NRC PDR	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 14

EC-1  
AK

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

July 30, 1992  
GO2-92-182  
Docket No. 50-397


Mr. J.B. Martin, Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596

Dear Mr. Martin:

Subject: WNP-2 OPERATING LICENSE NPF-21,  
RADIOLOGICAL ENVIRONMENTAL MONITORING  
PROGRAM SPECIAL REPORT

The attached nonroutine Radiological Environmental Monitoring Program report was written to fulfill the requirements of the Offsite Dose Calculation Manual (ODCM) Requirement For Operability 6.3.1.1. The Second Quarter 1992 average concentrations of iodine-131 and tritium in water sampled from the Plant 2 storm water drain exceeded the reporting levels listed in ODCM Table 6.3.1.1-2. An explanation of the problem, environmental sample results, and the causes are presented in the attached report.

Sincerely,

  
G.C. Sorensen, Manager  
Regulatory Programs (Mail Drop 280)

CJC:pk  
Attachment

cc:	RR Assa, NRC	NS Reynolds, Winston & Strawn
	JL Erickson, WDOH	NRC, Document Control Desk
	DL Williams, BPA (399)	JJ Zeller, EFSEC
	NRC Site Inspector (901A)	

500056

9208060167 920730  
PDR ADDCK 05000397  
R PDR

*Handwritten signature/initials*

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42