

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9210020042 DOC. DATE: 92/09/24 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH. NAME AUTHOR AFFILIATION
 BAKER, J.W. Washington Public Power Supply System
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 90-019-01, identified in response to Insp Rept
 50-397/90-20 w/expected submittal date of 910114. Rev
 delayed due to higher priority work. LER became part of LER
 suppl backlog.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+S
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES		
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL	
	PD5 LA		1	1		PD5 PD		1	1	
	DEAN, W.		1	1						
INTERNAL:	ACNW		2	2		ACRS		2	2	
	AEOD/DOA		1	1		AEOD/DSP/TPAB		1	1	
	AEOD/ROAB/DSP		2	2		NRR/DET/EMEB 7E		1	1	
	NRR/DLPQ/LHFB10		1	1		NRR/DLPQ/LPEB10		1	1	
	NRR/DOEA/OEAB		1	1		NRR/DREP/PRPB11		2	2	
	NRR/DST/SELB 8D		1	1		NRR/DST/SICB8H3		1	1	
	NRR/DST/SPLB8D1		1	1		NRR/DST/SRXB 8E		1	1	
	REG FILE 02		1	1		RES/DSIR/EIB		1	1	
	RGN5 FILE 01		1	1						
EXTERNAL:	EG&G. BRYCE, J.H		2	2		L ST LOBBY WARD		1	1	
	NRC PDR		1	1		NSIC MURPHY, G.A		1	1	
	NSIC POORE, W.		1	1		NUDOCS FULL TXT		1	1	

A04

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

September 24, 1992
602-92-223


Docket No. 50-397

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

**SUBJECT: NUCLEAR PLANT WNP-2, OPERATING LICENSE NPF-21
LICENSEE EVENT REPORT NO. 90-019-01**

Transmitted herewith is Licensee Event Report No. 90-019-01 for the WNP-2 Plant. This revision was identified in our response to Inspection Report 90-20 with an expected submittal date of January 14, 1991. This revision was initially awaiting the completion of a root cause analysis. Although the root cause was completed shortly after issuance of the original LER, the revision was delayed due to higher priority work. Eventually, it became part of an LER supplement "backlog". A supplemental LER has been committed, or needs to be evaluated, for approximately ten other issues. Management recognizes this supplemental "backlog" is inappropriate and is taking corrective action to resolve these items. This report is submitted in response to the report requirements of 10CFR50.73 and discusses the items of reportability, corrective action taken, and action taken to preclude recurrence.

Sincerely,



J. W. Baker
WNP-2 Plant Manager (Mail Drop 927M)

JWB/CLF/lr
Enclosure

cc: Mr. J. B. Martin, NRC - Region V
Mr. W. Ang, NRC Resident Inspector (Mail Drop 901A, 2 Copies)
INPO Records Center - Atlanta, GA
Mr. D. L. Williams, BPA (Mail Drop 399)

290082

9210020042 920924
PDR ADOCK 05000397
S PDR

IE22

111