

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9310040136 DOC. DATE: 93/09/27 NOTARIZED: NO DOCKET #
FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
AUTH. NAME AUTHOR AFFILIATION
PARRISH, J.V. Washington Public Power Supply System
RECIP. NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Responds to NRC 930726 ltr re violations noted in insp rept
50-397/93-19. Corrective actions: improvement of Plant
Procedure PPM 1.3.18, "Foreign Matl Control Around Spent
Fuel Pool, Reactor Cavity & Dryer Separator Pit."

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	PDV PD	1		CLIFFORD, J	1	
INTERNAL:	ACRS	2		AEOD/DEIB	1	
	AEOD/DSP/ROAB	1		AEOD/DSP/TPAB	1	
	AEOD/TTC	1		DEDRO	1	
	NRR/DORS/OEAB	1		NRR/DRCH/HHFB	1	
	NRR/DRIL/RPEB	1		NRR/DRSS/PEPB	1	
	NRR/PMAS/ILPB1	1		NRR/PMAS/ILPB2	1	
	NUDOCS-ABSTRACT	1		OE DIR	1	
	OGC/HDS1	1		REG FILE 02	1	
	RES/HFB	1		RGN5 FILE 01	1	
EXTERNAL:	EG&G/BRYCE, J.H.	1		NRC PDR	1	
	NSIC	1				

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 0





WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352-0968 • (509) 372-5000

September 27, 1993
GO2-93-238

Docket No. 50-397

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Gentlemen:

Subject: **WNP-2, OPERATING LICENSE NPF-21
REVISED RESPONSE TO INSPECTION REPORT 93-019**

Reference: Letter GO2-93-189, dated July 26, 1993, JV Parrish (SS) to NRC, "NRC Inspection Report 93-19 Response to Notice of Violation"

Included in the Supply System's response to Notice of Violation 93-019 are corrective actions designed to improve Plant Procedure PPM 1.3.18, "Foreign Material Control Around the Spent Fuel pool, the Reactor Cavity, and the Dryer Separator pit." These corrective actions incorporate lessons learned from our R8 outage and revise instructions for logging foreign materials. To improve this procedure further, a member of Plant Technical will be visiting the San Onofre Nuclear Power Station to observe implementation of their foreign material control program during their mid-October outage. To accommodate this visit, completion dates of all corrective actions stated in NOV 93-019 have been extended to November 30, 1993.

Sincerely,

J. V. Parrish (Mail Drop 1023)
Assistant Managing Director, Operations

KBL/bk

cc: BH Faulkenberry - NRC RV
NS Reynolds - Winston & Strawn
JW Clifford - NRC
DL Williams - BPA/399
NRC Site Inspector - 901A

010040

9310040136 930927
PDR ADDCK 05000397
G PDR



JE01
1/0