

ARIZONA




PUBLIC SERVICE COMPANY

P. O. BOX 21666 • PHOENIX, ARIZONA 85036

March 6, 1980

ANPP-14973-JAR



U. S. Nuclear Regulatory Commission  
Region V  
Walnut Creek Plaza - Suite 202  
1990 North California Boulevard  
Walnut Creek, California 94596

Attention: Mr. G. S. Spencer, Chief  
Reactor Construction and  
Engineering Support Branch

Subject: A 50.55(e) Reportable Condition Relating to Safety-  
Related Pipe Support Assemblies  
File: 80-019-026

Reference: Telephone Conversation between L. Vorderbrueggen  
and J. A. Roedel, January 31, 1980

Dear Sir:

Attached, is our final written report of the reportable deficiency under  
10CFR50.55(e) relating to safety-related pipe support assemblies installed  
in Unit #1 of the Palo Verde Nuclear Generating Station.

Very truly yours,

E. E. Van Brunt, Jr.  
APS Vice President  
Nuclear Projects  
ANPP Project Director

EEVBJr/JAR:skc

Attachment

cc: Victor Stello, Jr., Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

A. C. Gehr  
Snell & Wilmer

R. L. Robb  
L. W. Price  
W. E. Ide  
B. S. Kaplan  
W. H. Wilson  
W. G. Bingham  
J. E. Bashore  
W. J. Stubblefield

8004070255

80-10

