


*Central files*



**PUBLIC SERVICE COMPANY**

P. O. BOX 21666 • PHOENIX, ARIZONA 85036

March 11, 1980  
ANPP-15007 - JMA/WFQ

*AC/2*

Docket Nos. 50-528, 529, 530

Mr. R. H. Engelken, Director  
U.S. Nuclear Regulatory Commission  
Region V  
202 Walnut Creek Plaza  
1990 N. California Boulevard  
Walnut Creek, California 94591

Subject: NRC I&E Bulletin No. 79-28  
Possible Malfunction of Namco Model EA180  
Limit Switches at Elevated Temperature  
File: D.4.01.1; 80-005-026

Reference: (A) ANPP-14788 - JMA/WFQ dated February 8, 1980

Dear Mr. Engelken:

This letter serves to supplement our original response, Reference (A), to NRC I&E Bulletin No. 79-28.

We have determined that the subject limit switch is also supplied on a 1-1/2 inch pneumatic operated gate valve, CH-580, through a CE purchase order with Borg Warner. Please be advised that Borg Warner has been notified of the concern and has replaced the gaskets on the limit switches, prior to shipment of Valve CH580, as required by the subject Bulletin.

Very truly yours, .

*E.E. Van Brunt/SAC*

E. E. Van Brunt, Jr.  
APS Vice President,  
Nuclear Projects  
ANPP Project Director

EEVBJr/WFQ/av

cc: J. M. Allen  
J. A. Roedel  
F. W. Hartley  
W. H. Wilson  
C. Ferguson  
NRC Office of Inspection & Enforcement  
Division of Reactor Inspection Programs  
Washington, D.C. 20555

*T*

8007280 063

*Q*

