

ARIZONA




PUBLIC SERVICE COMPANY

P. O. BOX 21666 • PHOENIX, ARIZONA 85036

September 2, 1980

ANPP-16266 - JMA/WFQ

DOCKET NOS. 57-528,  
57-529  
57-530



Mr. R. H. Engelken, Director  
Nuclear Regulatory Commission  
Region V  
1990 N. California Boulevard  
Suite 202, Walnut Creek Plaza  
Walnut Creek, California 94596

Subject: NRC I&E Bulletin No. 80-19  
Failures of Mercury-Wetted Matrix Relays  
in Reactor Protective Systems of  
Operating Nuclear Power Plants Designed  
Combustion Engineering  
File: 80-055-026

Dear Mr. Engelken:

In reference to I&E Bulletin No. 80-19, CE does not use mercury-wetted relays in the PVNGS reactor protective system. A total of five manhours was used to perform this review.

Very truly yours,

*E. E. Van Brunt, Jr.*

E. E. Van Brunt, Jr.  
APS Vice President,  
Nuclear Projects  
ANPP Project Director

EEVBJr/WFQ/av.

cc: J. M. Allen  
F. W. Hartley  
C. Ferguson

NRC Office of Inspection & Enforcement

8010240 079

80-81

