

PRIORITY 1

(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9506290286 DOC.DATE: 95/06/22 NOTARIZED: NO DOCKET #
FACIL:STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi 05000529 P
AUTH.NAME AUTHOR AFFILIATION
LEVINE,J.M. Arizona Public Service Co. (formerly Arizona Nuclear Power R
RECIP.NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 95-001 re train A containment spray sys was
inoperable for more than 72 hs due to inoperable isolation
valve in sys. I
O

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+6 R
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:Standardized plant.

05000529 I

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
	PD4-2 PD	1 1	HOLIAN, B	1 1	T
	TRAN, L	1 1			Y
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2	
	AEOD/SPD/RRAB	1 1	FILE CENTER	1 1	1
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1	
	NRR/DE/EMEB	1 1	NRR/DISP/PIPB	1 1	
	NRR/DOPS/OECB	1 1	NRR/DRCH/HHFB	1 1	
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1	D
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SPSB/B	1 1	
	NRR/DSSA/SRXB	1 1	RES/DSIR/EIB	1 1	O
	RGN4 FILE 01	1 1			
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE,J H	2 2	C
	NOAC MURPHY,G.A	1 1	NOAC POORE,W.	1 1	
	NRC PDR	1 1	NUDOCS FULL TXT	1 1	U

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL
DESK, ROOM OWFN 5D8 (415-2083) TO ELIMINATE YOUR NAME FROM
DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 28 ENCL 28

AO-4

Arizona Public Service Company

PALO VERDE NUCLEAR GENERATING STATION
P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

192-00936-JML/BAG/KR

June 22, 1995

JAMES M. LEVINE
VICE PRESIDENT
NUCLEAR PRODUCTION

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, DC 20555-0001


Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 2
Docket No. STN 50-529 (License No. NPF-51)
Licensee Event Report 95-001-00**

Attached please find Licensee Event Report (LER) 95-001-00 prepared and submitted pursuant to 10CFR50.73. This LER reports a Technical Specification violation when the Train A Containment Spray System was inoperable for greater than 72 hours due to an inoperable isolation valve in the system.

In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the Regional Administrator, NRC Region IV. If you have any questions, please contact Burton A. Grabo, Section Leader, Nuclear Regulatory Affairs, at (602) 393-6492.

Sincerely,



JML/BAG/KR/pv

Attachment

cc: L. J. Callan (all with attachment)
K. E. Perkins
K. E. Johnston
INPO Records Center

9506290286 950622
PDR ADDCK 05000529
S PDR

