

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

AUTH.NAME	AUTHOR AFFILIATION
IDE,W.E.	Arizona Public Service Co. (formerly Arizona Nuclear Power
RECIP.NAME	RECIPIENT AFFILIATION
	Document Control Branch (Document Control Desk) <i>See</i>

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2 + 100
TITLE: OR Submittal: General Distribution

05000528 G
05000529
05000530 O

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD4-2 LA		1	1		PD4-2 PD		1	1
	FIELDS,M		1	1					
INTERNAL:	ACRS		1	1		FILE CENTER-01		1	1
	NRR/DE/ECGB/A		1	1		NRR/DE/EMCB		1	1
	NRR/DRCH/HICB		1	1		NRR/DSSA/SPLB		1	1
	NRR/DSSA/SRXB		1	1		NUDOCS-ABSTRACT		1	1
	OGC/HDS2		1	0					
EXTERNAL:	NOAC		1	1		NRC PDR		1	1

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 13

MAZ



Palo Verde Nuclear
Generating Station

William E. Ide
Vice President
Nuclear Engineering

TEL 602/393-6116
FAX 602/393-6077

Mail Station 7605
P.O. Box 52034
Phoenix, AZ 85072-2034

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, DC 20555-0001

102-04127-WEI/SAB/RKR
May 18, 1998

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS)
Units 1, 2, and 3
Docket Nos. STN 50-528/529/530
AT&T Round Cell Battery Equipment
Root Cause of Failure Analysis**

The NRC staff requested a copy of the Equipment Root Cause of Failure Analysis for AT&T round cell batteries. Attached is the Equipment Root Cause of Failure Analysis that includes the battery test program results. Please contact Mr. Scott Bauer at (602) 393-5978 if you have any questions or would like additional information regarding this matter. No commitments are being made to the NRC by this letter.

Sincerely,

WEI/SAB/RKR/rjh

Attachment

cc: E. W. Merschoff
M. B. Fields
K. E. Perkins
J. H. Moorman
S. N. Saba

11
11
A001

9805270378 980518
PDR ADDCK 05000528
P PDR

ATTACHMENT

Equipment Root Cause of Failure Analysis

