

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9806160053 DOC. DATE: 98/06/05 NOTARIZED: NO DOCKET #
 FACIL: STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi 05000528
 AUTH. NAME AUTHOR AFFILIATION
 IDE, W.E. Arizona Public Service Co. (formerly Arizona Nuclear Power
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 98-006-00 reporting condition where HPSI pump
 discharge check valves were misaligned which resulted in
 unacceptable reverse flow. Supplemental LER will be submitted
 by 980807.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 8
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: STANDARDIZED PLANT

05000528

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD4-2 PD	1 1	FIELDS, M	1 1
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2
	AEOD/SPD/RRAB	1 1	FILE CENTER	1 1
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	RES/DET/EIB	1 1	RGN4 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
 DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25

A04





Palo Verde Nuclear
Generating Station

William E. Ide
Vice President
Nuclear Engineering

TEL 602/393-6116
FAX 602/393-6077

Mail Station 7605
P.O. Box 52034
Phoenix, AZ 85072-2034

192-01021-WEI/DGM/RAS
June 5, 1998

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, D.C. 20555-0001

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Units 1, 2 and 3
Docket No. STN 50-528, 50-529, 50-530
License No. NPF-41, NPF-51, NPF-74
Licensee Event Report 98-006-00

Attached please find Licensee Event Report (LER) 98-006-00 prepared and submitted pursuant to 10 CFR 50.73. This LER reports a condition where the High Pressure Safety Injection pump discharge check valves were misaligned resulting in unacceptable reverse flow. The LER contains specific commitments for correcting the condition and a supplement to this LER will be submitted by August 7, 1998.

In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the Regional Administrator, NRC Region IV. If you have any questions, please contact Daniel G. Marks, Section Leader, Regulatory Affairs, at (602) 393-6492.

Sincerely,

WEI/DGM/RAS/rh

Attachment

cc: E. W. Merschoff (all with attachment)
K. E. Perkins
J. H. Moorman
INPO Records Center

9806160053 980605
PDR ADDCK 05000428
S PDR

1/1
IE22

