


REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

05000528^E

C
A
T
E
G
O
R
Y
1

D
O
C
U
M
E
N
T

A04





Palo Verde Nuclear
Generating Station

Gregg R. Overbeck
Vice President
Nuclear Production

TEL 602/393-5148
FAX 602/393-6077

Mail Station 7602
P.O. Box 52034
Phoenix, AZ 85072-2034

192-01027-GRO/DGM/REB
September 3, 1998

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, D.C. 20555-0001

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Units 1, 2 and 3
Docket No. STN 50-528, 50-529, 50-530
License No. NPF-41, NPF-51, NPF-74
Licensee Event Report 98-006-00

Attached please find Supplement 1 to Licensee Event Report (LER) 98-006-00 prepared and submitted pursuant to 10 CFR 50.73. This LER supplement reports a condition where the High Pressure Safety Injection pump discharge check valves were misaligned resulting in unacceptable reverse flow. The LER contains specific commitments for correcting the condition.

In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the Regional Administrator, NRC Region IV. If you have any questions, please contact Daniel G. Marks, Section Leader, Regulatory Affairs, at (602) 393-6492.

Sincerely,

GRO/DGM/REB/rjh

Attachment

cc: E. W. Merschoff (all with attachment)
M. B. Fields
J. H. Moorman
INPO Records Center

9809100277 980903
PDR ADDCK 05000528
S PDR

11
JE22

