

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9809140261	DOC.DATE: 98/09/08	NOTARIZED: NO	DOCKET #
FACIL:STN-50-529	Palo Verde Nuclear Station, Unit 2, Arizona Publi	05000529	
AUTH.NAME	AUTHOR AFFILIATION		
OVERBECK, G.R.	Arizona Public Service Co. (formerly Arizona Nuclear Power		
RECIP.NAME	RECIPIENT AFFILIATION		
	Records Management Branch (Document Control Desk)		

**SUBJECT:** Forwards LER 98-003-01, per 10CFR50.73. Revised LER provides cause & corrective action for delay in bypassing failed instrument used in plant PPS.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 6  
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: Standardized plant.

05000529<sup>E</sup>

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL	ID CODE/NAME		LTTR	ENCL
	PD4-2 PD		1	1	FIELDS,M		1	1
INTERNAL:	ACRS		1	1	AEOD/SPD/RAB		2	2
	AEOD/SPD/RRAB		1	1	<del>FILE CENTER</del>		1	1
	NRR/DE/ECGB		1	1	NRR/DE/EELB		1	1
	NRR/DE/EMEB		1	1	NRR/DRCH/HICB		1	1
	NRR/DRCH/HOHB		1	1	NRR/DRCH/HQMB		1	1
	NRR/DRPM/PECB		1	1	NRR/DSSA/SPLB		1	1
	RES/DET/EIB		1	1	RGN4 FILE 01		1	1
EXTERNAL:	L ST LOBBY WARD		1	1	LITCO BRYCE,J H		1	1
	NOAC POORE,W.		1	1	NOAC QUEENER,DS		1	1
	NRC PDR		1	1	NUDOCS FULL TXT		1	1

C  
A  
T  
E  
G  
O  
R  
Y  
1  
  
D  
O  
C  
U  
M  
E  
N  
T

**NOTE TO ALL "RIDS" RECIPIENTS:**

NOTE TO ALL "RIDS" RECIPIENTS:  
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS  
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL  
DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23

AD4:





Palo Verde Nuclear  
Generating Station

Gregg R. Overbeck  
Vice President  
Nuclear Production

TEL 602/393-5148  
FAX 602/393-6077

Mail Station 7602  
P.O. Box 52034  
Phoenix, AZ 85072-2034

192-01028-GRO/DGM/RAB  
September 8, 1998

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Mail Station P1-37  
Washington, D.C. 20555-0001

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS)**  
**Unit 2**  
**Docket No. STN 50-529**  
**License No. NPF-41**  
**Licensee Event Report 98-003-01**

Attached please find Licensee Event Report (LER) 98-003-01 prepared and submitted pursuant to 10 CFR 50.73. This LER supplement provides the cause and corrective action for the delay in bypassing a failed instrument used in the Plant Protection System.

In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the Regional Administrator, NRC Region IV. If you have any questions, please contact Daniel G. Marks, Section Leader, Regulatory Affairs, at (602) 393-6492.

Sincerely,

GRO/DGM/RAB/rlh

Attachment

cc: E. W. Merschoff (all with attachment)  
J. H. Moorman  
M. B. Fields  
INPO Records Center

9809140261 980908  
PDR ADOCK 05000529  
S PDR

