

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9811180071 DOC.DATE: 98/11/09 NOTARIZED: NO DOCKET #
FACIL:STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi 05000528
AUTH.NAME AUTHOR AFFILIATION
OVERBECK,G.R. Arizona Public Service Co. (formerly Arizona Nuclear Power
RECIP.NAME RECIPIENT AFFILIATION
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-003-01, IAW 10CFR50.73. Intermin corrective actions which were implemented to control FBT blocking, have subsequently been discontinued based upon more recent analysis.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: STANDARDIZED PLANT

05000528

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	ENCL
PD4-2 PD	1	1	FIELDS,M	1	1		
INTERNAL: ACRS	1	1	AEOD/SPD/RAB	2	2		
AEOD/SPD/RRAB	1	1	FILE CENTER	1	1		
NRR/DE/ECGB	1	1	NRR/DE/EELB	1	1		
NRR/DE/EMEB	1	1	NRR/DRCH/HICB	1	1		
NRR/DRCH/HOHB	1	1	NRR/DRCH/HQMB	1	1		
NRR/DRPM/PECB	1	1	NRR/DSSA/SPLB	1	1		
RES/DET/EIB	1	1	RGN4 FILE 01	1	1		
EXTERNAL: L ST LOBBY WARD	1	1	LITCO BRYCE, J H	1	1		
NOAC POORE, W.	1	1	NOAC QUEENER, DS	1	1		
NRC PDR	1	1	NUDOCS FULL TXT	1	1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23

AD4



Palo Verde Nuclear
Generating Station

Gregg R. Overbeck
Vice President
Nuclear Production

TEL 602/393-5148
FAX 602/393-6077

Mail Station 7602
P.O. Box 52034
Phoenix, AZ 85072-2034

192-01035-GRO/DGM/RAS
November 9, 1998

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, DC 20555-0001

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Units 1, 2, and 3
Docket Nos. STN 50-528/529/530
License Nos. NPF-41/51/74
Supplement to Licensee Event Report 98-003

Attached please find supplement 1 to Licensee Event Report (LER) 98-003 prepared and submitted pursuant to 10 CFR 50.73. This LER reports a previously unanalyzed condition which existed during periods when automatic fast bus transfer (FBT) capability was blocked to prevent the transfer of non-class plant equipment from the unit auxiliary transformer to the startup transformer.

This condition is no longer an unanalyzed condition because subsequent analysis has demonstrated that none of the Anticipated Operational Occurrences or Design Basis Events require FBT to be functional in order to mitigate the consequences or meet acceptance criteria for any accident. Interim corrective actions which were implemented to control FBT blocking, have subsequently been discontinued based upon the more recent analysis. APS makes no new regulatory commitments as a result of this LER supplement.

In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the Regional Administrator, NRC Region IV. If you have questions regarding this submittal, please contact Daniel G. Marks, Section Leader, Regulatory Affairs, at (602) 393-6492.

Sincerely,

GRO/DGM/RAS/rth

11/09/98

9811180071 981109
PDR ADOCK 05000528
S PDR

