

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9903040327	DOC.DATE: 99/02/23	NOTARIZED: NO	DOCKET #
FACIL:STN-50-528	Palo Verde Nuclear Station, Unit 1, Arizona Publi		05000528
STN-50-529	Palo Verde Nuclear Station, Unit 2, Arizona Publi		05000529
STN-50-530	Palo Verde Nuclear Station, Unit 3, Arizona Publi		05000530
AUTH.NAME	AUTHOR AFFILIATION		
OVERBECK,G.R.	Arizona Public Service Co. (formerly Arizona Nuclear Power		
RECIP.NAME	RECIPIENT AFFILIATION		
	Records Management Branch (Document Control Desk)		

SUBJECT: Advises that KP Jarvis, license OP-50287-1, no longer needs to maintain license as permanently assigned to position requiring no license.

DISTRIBUTION CODE: M003D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
TITLE: Operator Regualification Program

NOTES:STANDARDIZED PLANT	05000528
Standardized plant.	05000529
Standardized plant.	05000530

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID	CODE/NAME	LTTR	ENCL	ID	CODE/NAME	LTTR	ENCL
PD4-2	PD	1	1		FIELDS, M	1	1
INTERNAL:	ACRS	1	1		<del>FILE-CENTER-01</del>	1	1
	NRR/DRCH/HOHB	1	1		RGN4	1	1
EXTERNAL:	NOAC	1	1		NRC PDR	1	1

NOTE TO ALL "RIDS" RECIPIENTS:  
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS  
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL  
DESK (DCD) ON EXTENSION 415-2083

**TOTAL NUMBER OF COPIES REQUIRED: LTTR 8 ENCL**



10CFR55.55

Palo Verde Nuclear  
Generating Station

Gregg R. Overbeck  
Vice President,  
Nuclear Production

TEL 602/393-5148  
FAX 602/393-6077

Mail Station 7602  
P.O. Box 52034  
Phoenix, AZ 85072-2034

102-04247-GRO/DGM/RJH  
February 23, 1999

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Mail Station P1-37  
Washington, DC 20555-0001

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS).  
Units 1, 2, and 3  
Docket No. STN 50-528/529/530  
Expiration of Reactor Operator License**

Please be advised that Arizona Public Service Company (APS) has determined that Kevin P. Jarvis, (Docket Number 55-50442; License Number OP-50287-1) no longer needs to maintain a license. In accordance with 10CFR50.74, APS is providing notification that Mr. Jarvis has been permanently reassigned to a position that does not require a license, and requests that this individual's license be expired per 10CFR55.55.

If you have questions regarding this request, please contact Daniel G. Marks, Section Leader, Regulatory Affairs, at (602) 393-6492.

Sincerely,

GRO/DGM/RJH/mah

cc: E. W. Merschoff  
J. L. Pellet  
M. B. Fields  
J. H. Moorman

9903040327 990223  
PDR ADDCK 05000528  
V PDR

000040

M003 / 0

1. The first step is to identify the problem.
 2. The second step is to define the problem.
 3. The third step is to analyze the problem.
 4. The fourth step is to develop a solution.
 5. The fifth step is to implement the solution.
 6. The sixth step is to evaluate the solution.
 7. The seventh step is to monitor the solution.
 8. The eighth step is to maintain the solution.
 9. The ninth step is to improve the solution.
 10. The tenth step is to document the solution.