

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 050-316 Cook-2
 RECIPIENT: Keppler, J.G.
 ORIGINATOR: Shaller, D.V.
 COMPANY NAME: In & Mi Pwr
 SUBJECT:

DOC DATE: 781011
 ACCESSION NBR: 7810180027
 COPIES RECEIVED:
 LTR 3 ENCL 3
 SIZE: 3 + 1

LER#78-069/03L-0 on 780913: While performing surveillance test on protec
 set 4 pressurizer pressure high, reactor trip bistable failed to trip
 on simulated high pressure signal due to bad triac. Bistable was replaced.

DISTRIBUTION CODE: A002
 DISTRIBUTION TITLE:
 INCIDENT REPORTS

NOTARIZED

NAME	ENCL?
BR CHIEF	W/4 ENCL
<u>REG FILE</u>	<u>W/ENCL</u>
NRC PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
EMERGENCY PLAN BR	W/ENCL
NOVAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
VOLLMER/BUNCH	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
K SEYFRIT/IE	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION

ORB#1 BC

TOTAL NUMBER OF COPIES REQUIRED:

LTR 44
 ENCL 44

NOTES: Send 3 copies of all material to I&E.

OCT 19 1978

AO 4
 60

A002

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 050-316 Cook-2
RECIPIENT: Keppler, J.G.
ORIGINATOR: Shaller, D.V.
COMPANY NAME: In & Mi Pwr
SUBJECT:

DOC DATE: 781011
ACCESSION NBR: 7810180027
COPIES RECEIVED:
LTR 3 ENCL 3
SIZE: 3 + 1

LER#78-070/03L-0 on 780911: Air start line of 2AB diesel was found to be hot during load test due to loose piston bolt letting combustion vapors in air starting line. Check valve was replaced & engine retested satisfactorily.

DISTRIBUTION CODE: A002
DISTRIBUTION TITLE:
INCIDENT REPORTS

NOTARIZED

NAME.	ENCL?	FOR ACTION
BR CHIEF	W/4 ENCL	ORB#1 BC
REG FILE	W/ENCL	
NRC PDR	W/ENCL	
I & E	W/2 ENCL	
MIPC	W/3 ENCL	
I & C SYSTEMS BR	W/ENCL	
EMERGENCY PLAN BR	W/ENCL	
NOVAK/CHECK	W/ENCL	
EEB	W/ENCL	
AD FOR ENG	W/ENCL	
PLANT SYSTEMS BR	W/ENCL	
HANAUER	W/ENCL	
AD FOR PLANT SYSTEMS	W/ENCL	
AD FOR SYS & PROJ	W/ENCL	
REACTOR SAFETY BR	W/ENCL	
ENGINEERING BR	W/ENCL	
VOLLMEYER/BUNCH	W/ENCL	
KREGER/J. COLLINS	W/ENCL	
POWER SYS BR	W/ENCL	
K SEYFRIT/IE	W/ENCL	
LPDR	W/ENCL	
NSIC	W/ENCL	
ACRS	W/16 ENCL	

TOTAL NUMBER OF COPIES REQUIRED:

LTR 44
ENCL 44

NOTES:

REGULATORY DOCKET FILE COPY



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

October 11, 1978

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications
the following reports are submitted:

RO 78-069/03L-0
RO 78-070/03L-0.

Sincerely,

for D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R. Kilburn
R.J. Vollen BPI
K.R. Baker RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
J.M. Hennigan
G. Olson
PNSRC
J.F. Stietzel
Dir., IE (30 copies)
Dir., MIPC (3 copies)

REGULATORY DOCKET FILE 50-316

7810 18 0027