

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 050-315,316 Cook 1/2
 RECIPIENT: Keppler, J.G.
 ORIGINATOR: Shaller, D.V.
 COMPANY: IN & ME Pwr
 SUBJECT:

DOC DATE: 781030
 ACCESSION NBR: 7811020252
 COPIES RECEIVED:
 LTR 1 ENCL 0
 SIZE: 1

On 781030, it became necessary to isolate deluge valves to facil Drumming Room & New Fuel Receiving Area as result of repair on Five Sys headers. Follow up rept will be issued 781110.

DISTRIBUTION CODE: A001
 DISTRIBUTION TITLE:

NOTARIZED

GENERAL DISTRIBUTION FOR AFTER ISSUANCE OF OPERATING LICENSE.

| NAME | ENCL? | FOR ACTION |
|---------------------|-----------|------------|
| BR CHIEF | W/7 ENCL | • ORB#1 BC |
| REG FILE | W/ENCL | |
| NRC PDR | W/ENCL | |
| I & E | W/3 ENCL | |
| OELD | LTR ONLY | |
| HANAUER | W/ENCL | |
| CORE PERFORMANCE BR | W/ENCL | |
| AD FOR SYS & PROJ | W/ENCL | |
| ENGINEERING BR | W/ENCL | |
| REACTOR SAFETY BR | W/ENCL | |
| PLANT SYSTEMS BR | W/ENCL | |
| EEB | W/ENCL | |
| EFFLUENT TREAT SYS | W/ENCL | |
| J MCGOUGH | W/ENCL | |
| LPDR | W/ENCL | |
| TERA | W/ENCL | |
| NSIC | W/ENCL | |
| ACRS | W/16 ENCL | |

TOTAL NUMBER OF COPIES REQUIRED:

LTR 40
 ENCL 39

NOTES: I & E - 3 cys all material.

NOV 7 1978

MA 4
 6D



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

October 30, 1978

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58/DPR-74
Docket Nos. 50-315/50-316

Dear Mr. Keppler:

This is to confirm our verbal report to NRC Region III Inspector,
Mr. K.R. Baker, at 0830 hours on October 30, 1978.

At that time we reported that due to a repair on our Fire System
headers it became necessary to isolate the deluge valves to the Plant's
Drumming Room and New Fuel Receiving Area. This report is being made
in compliance with the ACTION statement of Fire Suppression Technical
Specification Sections 3.7.9.1 and 3.7.9.2.

A followup report will be submitted by November 10, 1978, as required
by Technical Specification 6.9.2.

Sincerely,

D.V. Shaller
Plant Manager

REGULATORY DOCKET FILE COPY

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R. Kilburn
R.J. Vollen BPI
K.R. Baker RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.

R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
J.M. Hennigan
PNSRC
J.F. Stietzel
Dir., IE (40 copies)
Dir., MIPC (4 copies)

781102. 0252

Approved
S/O



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

October 30, 1978

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58/DPR-74
Docket Nos. 50-315/50-316

Dear Mr. Keppler:

This is to confirm our verbal report to NRC Region III Inspector,
Mr. K.R. Baker, at 0830 hours on October 30, 1978.

At that time we reported that due to a repair on our Fire System
headers it became necessary to isolate the deluge valves to the Plant's
Drumming Room and New Fuel Receiving Area. This report is being made
in compliance with the ACTION statement of Fire Suppression Technical
Specification Sections 3.7.9.1 and 3.7.9.2.

A followup report will be submitted by November 10, 1978, as required
by Technical Specification 6.9.2.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R. Kilburn
R.J. Vollen BPI
K.R. Baker RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.

R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
J.M. Hennigan
PNSRC
J.F. Stietzel
Dir., IE (40 copies)
Dir., MIPC (4 copies)

DUPE

781120°252 S

NOV 1 1978

A002
5/10

