

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5						
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32						
LICENSEE CODE														LICENSE NUMBER										LICENSE TYPE				CAT		58	

0	1	L	0	5	0	0	0	3	1	6	7	1	0	1	9	7	8	8	1	1	0	8	7	8	9
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
CON'T		REPORT SOURCE		DOCKET NUMBER										EVENT DATE						REPORT DATE					

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 WHILE ATTEMPTING TO PROVE OPERABILITY OF 2AB EMERG. DIESEL IN ORDER TO REMOVE
0 3 2CD DIESEL FROM SERVICE, THE ENGINE FAILED TO START. THIS CONSTITUTED AN IN-
0 4 OPERABLE POWER SOURCE PER T.S. 3.8.1.1. INVESTIGATION REVEALED APPARENT LACK
0 5 OF FUEL TO THE INJECTOR PUMPS. ENGINE WAS AGAIN TESTED AND DID START ON THE
0 6 THIRD ATTEMPT. FUEL FILTER ELEMENT WAS REMOVED AND INSPECTED. CONDITION OF
0 7 ELEMENT APPEARED SATISFACTORY, BUT A NEW ELEMENT WAS INSTALLED. ENGINE WAS
0 8 INOPERABLE FOR 27 MINUTES. NO PROBABLE CONSEQUENCES.

0	9	E	E	11	E	12	B	13	E	N	G	I	N	E	14	Z	15	Z	16	17	7	8	0	7	9	0	3	L	0	W	3	1	4	26
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE								COMP. SUBCODE		VALVE SUBCODE		LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE CAUSE FOR THE APPARENT LACK OF FUEL COULD NOT BE DETERMINED. FOLLOW-
1 1 ING THE ACTION DESCRIBED IN ITEM 10 ABOVE, THE ENGINE STARTED SATISFACTO-
1 2 RILY AND HAS CONTINUED TO DO SO ON NUMEROUS OCCASSIONS SUBSEQUENT TO THE
1 3 EVENT. SINCE THIS IS THE FIRST OCCURRENCE OF THIS TYPE, NO FURTHER ACTION
1 4 IS PLANNED.

1	5	E	28	0	9	0	29	NA	B	31	REDUNDANT EQUIPMENT OPERABILITY TEST	32	
7	8	9	10	11	12	13	14	15	16	17	18	19	
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
ACTIVITY CONTENT RELEASED		AMOUNT OF ACTIVITY		LOCATION OF RELEASE		PERSONNEL EXPOSURES		PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY		PUBLICITY	
NUMBER		TYPE		DESCRIPTION		NUMBER		DESCRIPTION		TYPE		DESCRIPTION	

1 6 Z 33 Z 34 NA NA NA
1 7 0 0 0 37 Z 38 NA
1 8 0 0 0 40 NA
1 9 Z 42 NA
2 0 N 44 NA

7811140232

NAME OF PREPARER D.G. WIZNER

PHONE: 616-465-5901, EXT. 398

Handwritten marks and scribbles in the top right corner.



Small handwritten marks or scribbles in the bottom left area.

Small handwritten marks or scribbles near the bottom left corner.