

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	6	7	1	0	2	3	7	8	8	1	1	2	2	7	8	9
60	61								68	69						74	75							80
DOCKET NUMBER										EVENT DATE								REPORT DATE						

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

09		SYSTEM CODE S F		CAUSE CODE X		CAUSE SUBCODE Z		COMPONENT CODE A C C U M U				COMP. SUBCODE Z		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
LER/RO REPORT NUMBER		EVENT YEAR 7 8		SEQUENTIAL REPORT NO. 0 8 1		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN Z		FUTURE ACTION Z	
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38
EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0		ATTACHMENT SUBMITTED Y		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER N		COMPONENT MANUFACTURER W 1 2 0		REVISION NO. 0	
39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
1	5	E	28	0	9	0	29	NA	30	B	31	ROUTINE SAMPLES	32
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE							
1	6	Z	33	1	0	34	NA	35	36	NA			

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	0	0	0
2	0	0	0
3	0	0	0
4	0	0	0
5	0	0	0
6	0	0	0
7	0	0	0
8	0	0	0
9	0	0	0
10	0	0	0
11	0	0	0
12	0	0	0
13	0	0	0
14	0	0	0
15	0	0	0
16	0	0	0
17	0	0	0
18	0	0	0
19	0	0	0
20	0	0	0
21	0	0	0
22	0	0	0
23	0	0	0
24	0	0	0
25	0	0	0
26	0	0	0
27	0	0	0
28	0	0	0
29	0	0	0
30	0	0	0
31	0	0	0
32	0	0	0
33	0	0	0
34	0	0	0
35	0	0	0
36	0	0	0
37	0	0	0
38	0	0	0
39	0	0	0
40	0	0	0
41	0	0	0
42	0	0	0
43	0	0	0
44	0	0	0
45	0	0	0
46	0	0	0
47	0	0	0
48	0	0	0
49	0	0	0
50	0	0	0
51	0	0	0
52	0	0	0
53	0	0	0
54	0	0	0
55	0	0	0
56	0	0	0
57	0	0	0
58	0	0	0
59	0	0	0
60	0	0	0
61	0	0	0
62	0	0	0
63	0	0	0
64	0	0	0
65	0	0	0
66	0	0	0
67	0	0	0
68	0	0	0
69	0	0	0
70	0	0	0
71	0	0	0
72	0	0	0
73	0	0	0
74	0	0	0
75	0	0	0
76	0	0	0
77	0	0	0
78	0	0	0
79	0	0	0
80	0	0	0
81	0	0	0
82	0	0	0
83	0	0	0
84	0	0	0
85	0	0	0
86	0	0	0
87	0	0	0
88	0	0	0
89	0	0	0
90	0	0	0
91	0	0	0
92	0	0	0
93	0	0	0
94	0	0	0
95	0	0	0
96	0	0	0
97	0	0	0
98	0	0	0
99	0	0	0
100	0	0	0

1	9	42	NA	
7	8	9	10	80
PUBLCITY			45	NRC USE ONLY

ISSUED DESCRIPTION

	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
2	0	N	(44)	NA																				

68 69 80

100-45

(12) 165-5003

**NRC USE ONLY**

185  
NAME OF PREPARER J. M. Randolph

PHONE: (616) 465-5901



ATTACHMENT TO LER #78- 081/03L-0

**SUPPLEMENT TO CAUSE DESCRIPTION AND CORRECTIVE ACTIONS**

THE APPLICABLE PROCEDURES FOR TRANSFER OF BORIC ACID SOLUTION HAVE BEEN CHANGED  
TO REDUCE THE PROBABILITY OF NON-UNIFORM BORON CONCENTRATIONS.