

REGULATOR INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 50-316 COOK 2
 RECIPIENT: KEPLER, J.G.
 ORIGINATOR: SHALLER, D.V.
 COMPANY NAME: IND & MI PWR CO
 SUBJECT:

DOC DATE: 781204
 ACCESSION NBR: 7812080086
 COPIES RECEIVED:
 LTR 1 ENCL 1
 SIZE: 1+1

LER#78-086/03L-0 on 780723: Snubber #63 was found to inverted on its horizontal axis during inspec due to loose rod end locknut. Snubber removed, tested & reinstalled.

DISTRIBUTION CODE: A002
 DISTRIBUTION TITLE:
 INCIDENT REPORTS

NOTARIZED

NAME	ENCL?
BR CHIEF	W/4 ENCL
REG EDIT	W/ENCL
NRC PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
NOVAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
E. Jordan	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION

ORB #1 BC

TOTAL NUMBER OF COPIES REQUIRED:

LTR
 ENCL

42
 42

NOTES:

DEC 11 1978

A0 4
 60



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

December 4, 1978

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications
the following report is submitted:

RO 78-086/03L-0.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R. Kilburn
R.J. Vollen BPI
K.R. Baker RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
J.M. Hennigan
PNSRC
J.F. Stietzel
Dir., IE (30 copies)
Dir., MIPC (3 copies)

DEC 11 1978

DUPE

7812080088

A002
11/11

