

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	2	0	0	-	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5			
7	8	LICENSEE CODE						14		LICENSE NUMBER											25	LICENSE TYPE					30			57	CAT	58

CON'T

0 1 7 8
REPORT SOURCE L 6 0 5 0 0 0 3 1 6 7 0 7 2 3 7 8 8 1 2 0 4 7 8 9
60 61 DOCKET NUMBER 68 69 EVENT DATE . 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | DURING A SURVEILLANCE INSPECTION, SNUBBER (NO. 63) WAS FOUND TO HAVE
0 3 | ROTATED 180° ON ITS HORZ. AXIS AND WAS DECLARED INOPERABLE PER T.S.
0 4 | 3.7.7.1. SINCE OPERABILITY IS NOT REQUIRED IN MODE 5, A REPORT WAS NOT
0 5 | SUBMITTED. A RECORD REVIEW DURING AN NRC INSPECTION INDICATED THAT THE
0 6 | SNUBBER MAY HAVE BEEN INOPERABLE DURING REACTOR OPERATIONS AND REPORTING
0 7 | IS MERITED. NO SEISMIC EVENTS HAVE BEEN RECORDED AND PUBLIC HEALTH AND
0 8 | SAFETY WERE NOT JEOPARDIZED.
7 8 9

SYSTEM CODE 9 10 Z Z (11)		CAUSE CODE 11 12 B (12)		CAUSE SUBCODE 12 13 B (13)		COMPONENT CODE 13 14 15 16 17 18 S U P P O R T (14)				COMP. SUBCODE 19 20 D (15)		VALVE SUBCODE 20 21 Z (16)	
L&R/RO REPORT NUMBER (17) 21 22 7 8		EVENT YEAR 23 24 —		SEQUENTIAL REPORT NO. 24 25 26 0 8 6		OCCURRENCE CODE 27 28 29 / 0 3		REPORT TYPE 30 31 L		REVISION NO. 32 33 0			
ACTION TAKEN 33 34 E (18)		FUTURE ACTION 34 35 Z (19)		EFFECT ON PLANT 35 36 Z (20)		SHUTDOWN METHOD 36 37 Z (21)		HOURS 37 38 39 40 0 0 0 0 (22)		ATTACHMENT SUBMITTED 41 42 N (23)		NPRD-4 FORM SUB. 42 43 N (24)	
PRIME COMP. SUPPLIER 43 44 A (25)		COMPONENT MANUFACTURER 44 45 46 47 I 2 0 7 (26)											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | SNUBBER WAS INVERTED DUE TO A LOOSE ROD END LOCKNUT, (LOCKNUT B IN ITT
1 1 | GRINNEL CATALOGUE PH-74, FIG. 201). SNUBBER WAS REMOVED, TESTED SATIS-
1 2 | FACTORILY AND REINSTALLED WITH PROPER ORIENTATION. THE LOCKNUT WAS
1 3 | TIGHTENED AND STAKED. CAUSE OF LOOSE LOCKNUT COULD NOT BE DETERMINED.
1 4 | NO OTHER SNUBBERS WERE FOUND TO BE INVERTED DURING THE INSPECTION.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

FACILITY STATUS (28) G

% POWER (29) 0 0 0

OTHER STATUS (30) NA

METHOD OF DISCOVERY (31) B

DISCOVERY DESCRIPTION (32) SURVEILLANCE TESTING

ACTIVITY RELEASED (33) Z

CONTENT OF RELEASE (34) Z

AMOUNT OF ACTIVITY (35) NA

LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	7	0	0	0
		(37)	Z	(38) NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1 8	0 0 0	(40)	NA

7		8		9		10		11		12	
				TYPE		DESCRIPTION					
1	9	Z	(42)	NA							

ISSUED		PUBLICATION		DESCRIPTION		NA		7812080089		NRC USE ONLY		
2	0	N	44									
7	8	9	10							68	69	80

NAME OF PREPARER M.S. BROWN

PHONE: 616-465-5901, EXT. 398

