

**LICENSEE EVENT REPORT**

**(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)**

**CON'T**

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

08 | \_\_\_\_\_

7 8 9

(17) LER/RO REPORT NUMBER    EVENT YEAR    SEQUENTIAL REPORT NO.    OCCURRENCE CODE    REPORT TYPE    REVISION NO.

7 8    0 9 3    0 3    L    0

21 22    23    24 25 26    27    28 29    30    31    32

ACTION TAKEN [E] 18 FUTURE ACTION [X] 19 EFFECT ON PLANT [Z] 20 SHUTDOWN METHOD [Z] 21 HOURS [0] [0] [0] [0] 22 ATTACHMENT SUBMITTED [N] 23 NPRD-4 FORM SUB. [N] 24 PRIME COMP. SUPPLIER [N] 25 COMPONENT MANUFACTURER [W] [1] [2] [0] 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	INVESTIGATION REVEALED THAT THE SIGNAL CONDITIONING MODULE HAD DRIFTED FOR H-8.
---	---	---

1 1 AFTER VERIFYING THE POSITION OF ROD H-8 BY MEASURING THE ROD'S SECONDARY COIL VOLTAGE,

1 2 THE SIGNAL CONDITIONING MODULE WAS ADJUSTED FOR THE PROPER OUTPUT AND RPI FOR H-8

1 3 WAS RETURNED TO SERVICE INDICATING THE CORRECT ROD POSITION. AN ENGINEERING REVIEW

1 4 IS IN PROGRESS TO DETERMINE THE ROOT CAUSE OF THIS RECURRING PROBLEM.

7	8	9											80																																																												
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION																																																																	
1	5	C	28	0	6	6	29	NA	B	31	OPERATOR OBSERVATION																																																														
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6  
7 8

Z 33

Z 34

AMOUNT OF ACTIVITY (35)

NA

45 80

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION						
1	7	0	0	0	(37)	Z	(38)	NA	(39)	

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	40 NA

7		8	9	11		12
		LOSS OF OR DAMAGE TO FACILITY		(43)		
TYPE		DESCRIPTION				
1	9	Z	(42)	NA		

7 8 9 10  
 PUBLICITY  
 ISSUED DESCRIPTION (45) 78 12270264 NRC USE ONLY  
 [2] [0] [N] (44) NA

NAME OF PREPARER J. L. Rischling

PHONE: 616-465-5901

