

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 1 2 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 5 7 0 6 2 3 7 8 8 0 1 1 6 7 9 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 WHILE IN MODE 2 THE INDICATED POSITION OF RODS C-3, C-13, N-13, H-6, F-8 AND  
0 3 K-8 INDICATED A DEVIATION OF GREATER THAN TWELVE STEPS FROM DEMAND POSITION.  
0 4 THIS IS IN EXCESS OF THE LIMIT IDENTIFIED BY T.S. 3.1.3.2 SIMILAR OCCURRENCES  
0 5 PREVIOUSLY SUBMITTED ARE: 0315/76-13, 44 AND 54; 0315/77-27,28,33, AND 34;  
0 6 0315/78-04,07 AND 0316/78-07,08,22,31 AND 41.  
0 7  
0 8

0 9 SYSTEM CODE 11 CAUSE CODE 12 CAUSE SUBCODE 13 COMPONENT CODE 14 COMP. SUBCODE 15 VALVE SUBCODE 16  
7 8 9 10 11 12 13 18 19 20  
17 LER/RO REPORT NUMBER 18 EVENT YEAR 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
0 18 0 19 0 20 0 21 0 22 0 23 0 24 0 25 0 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE CAUSE WAS TRACED TO THE SIGNAL CONDITIONING MODULES WHICH WERE RESPANNED  
1 1 AND SATISFACTORILY RETURNED TO SERVICE AFTER SECONDARY VOLTAGE WAS VERIFIED  
1 2 TO BE CORRECT PER POSITION DEMAND.  
1 3 THE EXTERNAL CAUSE OF INDICATOR DRIFT HAS NOT BEEN DETERMINED ALTHOUGH AN  
1 4 ENGINEERING REVIEW IS IN PROGRESS.  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 5 FACILITY STATUS 28 % POWER 29 0 0 4 30 OTHER STATUS 31 METHOD OF DISCOVERY 32 DISCOVERY DESCRIPTION 33  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 6 ACTIVITY CONTENT 33 RELEASED OF RELEASE 34 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 7 PERSONNEL EXPOSURES 37 NUMBER 38 TYPE 39 DESCRIPTION 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 8 PERSONNEL INJURIES 40 NUMBER 41 DESCRIPTION 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 9 LOSS OF OR DAMAGE TO FACILITY 43 TYPE 44 DESCRIPTION 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
2 0 PUBLICITY 45 ISSUED 46 DESCRIPTION 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

T. P. Beilman

NAME OF PREPARER

PHONE:

616-465-5901

NRC USE ONLY

