

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

NO PROBABLE CONSEQUENCES.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

BLOWDOWN RETURNING THEM TO SERVICE. (SEE SUPPLEMENT)

ACTIVITY	CONTENT
----------	---------

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES

PERSONNEL INJURIES

SS OF OR DAMAGE TO FACILITY

**TO
PUBLICITY**

PHONE:

ATTACHMENT TO LER #79-003/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

DURING PLANT STARTUP, THIS INSTRUMENTATION WAS MONITORED, INSURING IT FUNCTIONED PROPERLY. IT WAS ALSO DISCOVERED THAT THE UNIT 1 WEST STEAM ENCLOSURE VENT OPENING WAS NOT CLOSED OFF, THESE WERE ALSO CLOSED. TO PREVENT RECURRENCE THESE STEAM ENCLOSURE VENT OPENINGS WILL BE CLOSED AS THIS ITEM HAS BEEN ADDED TO A PRE-WINTER CHECK-OUT LIST.

