



1898

1898

SUPPLEMENT TO LER# 79-022/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

(FOXBORO, 63U-BC-OHEA-F), THE NEW BISTABLE WAS CALIBRATED AND RETURNED TO SERVICE. A RECHECK OF THE NEW BISTABLE ON JULY 14, VERIFIED THAT ALL SETPOINTS WERE IN SPEC.



1997