

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7912040390 DOC. DATE: 79/11/26 NOTARIZED: NO DOCKET #  
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 AUTH. NAME: AUTHOR AFFILIATION:  
 DELONG, S.D. Indiana & Michigan Power Co.  
 RECIP. NAME: RECIPIENT AFFILIATION:  
 Region 3, Chicago, Office of the Director

SUBJECT: LER 79-056/03L: on 791027, opening torque on two ice  
 condenser lower inlet doors exceeded max Tech Spec limit.  
 Caused by door springs slightly stiffer than doors on other  
 bays. Spring tension bolts adjusted.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 2  
 TITLE: Incident Reports

NOTES: I E - 3 cys ALL MATL

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL		ID CODE/NAME	LTTR
	05 BC ORB #1	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIELI	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	22 REAC SAFT BR	1	1
	23 ENGR BR	1	1	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 AD SITE ANAL	1	1
	27 OPERA LIC BR	1	1	28 ACIDENT ANALYS	1	1
	29 AOX SYS BR	1	1	E JORDAN/IEI	1	1
	HANAUER, S.	1	1	STS GROUP LEADR	1	1
	TMI-H STREET	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

DEC 5 1979

TOTAL NUMBER OF COPIES REQUIRED: LTTR

51 51  
 46 ENCL 46

AOLI  
 4

61

THE  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
WASHINGTON, D. C. 20250

TO: [illegible]  
FROM: [illegible]  
SUBJECT: [illegible]

[illegible text block]

[illegible text block]

[illegible text block]